



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI20011646/Asf3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-11-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7664C	Veh. Inspected	SFB 325G
Policy No.		Coverage (\$)	0.00
Claim No.	D20004331MFSH	Excess (\$)	0.00
Assign From	MERINA CHIA SAN SAN	Assign Date	27/10/2020

2. Vehicle Particulars & Condition

Make & Model	RENAULT FLUENCE	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1LZLF0E54491634	Colour	WHITE
Odometer	135615	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	6 mm
L/H Front Tyre	205/60 R16	TOYO	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/10/2020	Inspection Date	27/10/2020
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**