

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011649/KYF3E2

Date: 17/11/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00089252000
Claimant Vehicle No :	SML2697J	Insured Vehicle No :	GBB9686C
Date of Loss:	26/10/2020	Nature of Claim:	TP
		Claim No:	SNM20D204042/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML2697J	Engine No:	K9KF649D059676
Make & Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Chassis No:	VF1RFA00162672978
Reg. Date:	13/05/2019 (Man. Year: 2019)	Odometer:	100431 km
Colour:	Metallic Black		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R20	Rear Tyre Size:	195/55R20
Front Left Side:	Tourador 9 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Tourador 9 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,961.66	1,863.90	2,097.76	52.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	760.00	1,090.00	58.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,811.66	2,623.90	3,187.76	54.85
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	5,811.66	2,100.00	3,711.66	63.87
+ GST 7.00/7.00% (S\$)	406.82	147.00	259.82	63.87
Nett Amount (S\$)	6,218.48	2,247.00	3,971.48	63.87

INSPECTION

Date of Assignment:	27/10/2020	Inspected At:	
Date Inspected:	27/10/2020		Munich Autocare Pte Ltd (HQ) 60 JALAN LAM HUAT #06-43 CARROS CENTER SINGAPORE 737869
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2020)
Parts: M1-MPV	RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML2697J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*HEADLIGHT ASSY,LH	Cracked	1,016.40 FL	*820.50 FL	
2	1		*FRONT BUMPER ASSY	Buckled/Cut	1,461.72 FL	*1,250.50 FL	
3	1		*BUMPER RETAINER,LH	Serviceable	140.88 FL	*- FL	
4	1		*FENDER LH	Repair	747.12 FL	*- FL	
5	1		*20 RIM (SCRATCHED)	Not Consistent With The Impact	1,035.72 FL	*- FL	
					Sub Total (S\$)	4,401.84	2,071.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	440.18	207.10
					Total Parts (S\$)	3,961.66	1,863.90

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING LABOUR FOR DAMAGED AT LEFT FRONT AREA	New	800.00	300.00
2	WHEEL ALIGNMENT	New	100.00	0.00
3	ADJUST HEADLIGHT FOCUS	New	50.00	20.00
4	TRANSFER TYRE TO NEW RIM AND BALANCING NEW RIM	New	100.00	0.00
5	SPRAY PAINTING FOR FRONT BUMPER AND FRONT LEFT FENDER	New	800.00	440.00
			Gross Labour Cost (S\$)	760.00
			1,850.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >