

VEHICLE NO. SJW6302A

MERCEDES BENZ

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)		1480.00	1350 ✓
1	Front bumper / DD	? / BR	328.00	142 ✓
1	Front bumper LED daylight w/chrome LHS	? / BR	172.00	103 ✓
1	Front bumper LED daylight grille cover	? / CUT (LH)	204.00	102 ✓
21	Front bumper lower chrome moulding RH & LH @102	? / CUT (LH)	342.00	X
1	Front bumper centre lower grille X NM	? / BT	782.00	678 ✓
1	Front bumper reinforcement frame	? / BR	112.00	✓
1	Front bumper reinforcement foam cover	? / (LH) - BR	248.00	124 ✓
21	Front bumper side holder RH & LH @124.00	? / CUT (LH) - BR	375.00	X
1	Front bumper under cover	X NM	2250.00	X
1	Bonnet X Repair		248.00	X
2	Bonnet spring stopper @124.00 X NM		597.00	X
2	Bonnet inner lock lower @298.50 X NM		197.00	X
2	Bonnet inner lock catch @98.50 X NM		378.00	X
1	Bonnet insulator X NM		72.00	✓
1	Bonnet MERC. Badge / OPC		549.00	X
2	Bonnet dampers @274.50 X NM	? / BR	672.00	✓
1	Front centre radiator chrome grille	? / NM	98.00	X
1	Front centre radiator chrome grille badge X		985.00	897 ✓
1	LHS Front fender / BT (Aluminum)	? / TN	260.00	✓
1	LHS Front fender inner splash shield		372.00	X
1	Wiper washer tank X NM		1980.00	1610 ✓
1	LHS Headlamp ? / BR		324.00	X
1	LHS Headlamp top panel X NM		592.00	X
1	LHS Front Shock absorber X NM		198.00	X
1	LHS Front tie rod X NM		375.00	X
1	LHS Front Lower control arm X NM		375.00	X
1	LHS Front Upper control arm X NM		294.00	✓
1	LHS Front wheel bearing X Jammed		492.00	X
1	LHS Front knuckle arm X NM			
			15351.00	
		less 10%	1535.10	10%
			13815.90	
	SPECIAL NETT ITEMS			
1set	LHS Front fender inner splash shield clips	? / MC	80.00	20 ✓
1	LHS Front sports rim AF / CUT		1280.00	700 ✓
1	LHS Front tyre 80% X NM		280.00	X
1set	Bonnet insulator clips X NM		80.00	X
				720
	Total Parts		15535.90	

6416
-10%
5774.40

VEHICLE NO. SJW6302A MERCEDES BENZ

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR	1400.00	500
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components		
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	600
3	To remove and check wiring of all electrical components and focus headlamp beam	200.00	30
4	To clear fault code with diagnostic computer and reset to specifications	300.00	X
5	To remove and replace LHS Front undercarriage parts (suspension components)	300.00	50
6	To conduct full computerised wheel alignment test	120.00	60
7	To perform anti rust treatment on affected areas	150.00	30
	Labour Total :	3470.00	
	TOTAL (PARTS & LABOUR):	19005.90	1270

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

Steve CLKK) W- PL
27/10/20, 11.30am
4 days

L/S

My PL SL

P-5774.49

N-720

L-1270

7764.49

L/S-6211.52
= 6200

Let the Contractor hence notify the Repairer of the following:

- To resurvey after spray painting
- To replace damaged part(s) during resurvey
- Part replaced subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No time limit (days) is allowed
- Supplementary part(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: