

## ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS FOR VEHICLE NO: SMP 191T

### Adjustment of Spare Parts Costs for Repairs

Item	Qty	Vehicle parts description	Condition / Remark	Estimated by workshop	
1	1	Sliding Door (LH) ✓ DD		1650.00 ✓	
2	1	rear door moulding LH ✗ NN		455.00	
3	1	rear Door motor (LH) ✗ NN		1550.00	
4	1	rear Door Handle (LH) ✗ NN		230.00	
5	1	rear Door inner Lock LH ✗ NN		355.00	
6	1	rear door inner trim board LH ✗ NN		395.00	
7	1	rear door weatherstrip LH ✗ NN		298.00	
8	1	front door LH ✓ DD		1250.00 ✓	
9	1	front door inner trim board LH ✗ NN		325.00	
10	1	front door inner lock LH ✗ NN		355.00	
11	1	front door weatherstrip LH ✗ NN		298.00	
12	1	front door moulding LH ✗ NN		400.00	
13	1	rear LH fender ✗ Repair		990.00	
14	1	rear LH fender inner sheild ✓ TN		198.00 ✓	
15	1	rear LH fender inner sheild fasteners ✓ NEC		25.00 ✓	
16	1	rear bumper ✓ BR		750.00 ✓	
17	1	rear bumper LH side retainer ✓ BR		38.00 ✓	
18	1	rear bumper bracket LH ✗ NN		115.00	
19	1	rear LH absorber ✗ NN		325.00	
20	1	rear LH wheel bearing ✓ Jammed		698.00 422.60 ✓	
21	1	rear LH knuckle arm ✗ NN		670.00	
22	1	rear LH lower arm ✗ NN		620.00	
23	1	rear LH wheel hub ✗ NN		350.00	
				<hr/>	4333.60
				12340.00	-25%
Less 25%				3085.00	3250.20
				<hr/>	
				9255.00	
				<hr/>	

### Special Nett Item

1	1	Window moulding LH ✗ NN		85.00	
2	1	rear LH rim ✓ CUT		350.00 ✓	
3	1	rear LH tyre ✗ NN		280.00	
4	1	reverse sensor ✗ NN		200.00	
5	1	front LH door chrome moulding ✓ CUT		200.00 ✓	
6	1	rear LH door chrome moudling ✓ CUT		200.00 ✓	
7	1	front LH door side skirt garnish ✓ BR		200.00 ✓	
8	1	rear LH door side skirt garnish ✓ BR		200.00 ✓	
9	1	rear LH door side skirt corner garnish ✓ BR		120.00 ✓	
					1270

### Adjustment of Labour Costs for Repairs

To remove and replaced damaged parts including straightening and

repositioning replacement parts.	1200.00	1100	
Supply paint material and necessary items. To respray replaced and other affected panels.	1000.00	✓	
To remove n replace front and rear door components	250.00	100	
To check wiring system for proper functions.	60.00	30	
To dismantle & refix front and rear door window	250.00	100	
To carry out anti rust treatment.	150.00	30	
to remove and reinstall rear LH undercarriage item	250.00	100	
to remove and refix reverse sensor	80.00	30	
to perform 4 wheel alignment	100.00	60	
to remove and reinstall fuel components	150.00	×	
to remove and reinstall rear LH windscreen	120.00	×	2550
<b>Total labour</b>	<b>3610.00</b>		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Steve (LKK)  
28/10/20  
Without Prejudice  
Lumpsum  
Resurvey After Spray  
6 repair days

P - 3250.20  
N - 1270  
L - 2550  
7070.20  
  
L/S - 5656.16  
= 5650

12865.00