

L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748

WORKSHOP ESTIMATE

Rear bumper	damaged
Rear bumper reinforcement	fractured
Rear bumper reinforcement bracket	serviceable
Sensor	malfunction
Labour charges	
Spray	
Anti rust	
replace sensor	

Repair Cost Summary			
Hua Meng Spray Painting Workshop Assessment Excluding GST		LBS Auto Consultants Pte Ltd Assessment Excluding GST	
Labour:	NIL	Labour:	\$700.00
Paint Labour:	NIL	Paint Labour:	\$500.00
Parts:	NIL	Parts:	\$1,000.00
Total:	NIL	Total:	\$2,200.00
Lump Sum Less 20%:		Lump Sum Less 20%:	
The repairs will take 04 working days to complete.			

L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748

Vehicle Survey Report			
Insurer:	Direct Asia Insurance (Singapore) Pte. Ltd.	Claim Number:	96308
Workshop:	Hua Meng Spray Painting Workshop	Claim Type:	PRI
Vehicle make & model:	Hyundai Avante	Vehicle number:	SJR7374L Engine Capacity:1591
Registration date:	13.07.2009	Vehicle Mileage:	115730
Chassis No:	KMH DU41BR9U774252	Engine No:	G4FC9U663367
Economic Repair Limit	Market Value: \$38,000.00 PARF/COE Rebate: \$24,221.00 Repair Limit: \$13,879.00	Part by Part Repair or Lump Sum Repair:	Part by Part Repair
Workshop Estimate Cost:	NIL	Surveyor Estimated Repair Cost:	SGD \$2,200.00 + GST
Days to Repair:	04 days	OD Excess Applicable:	NIL
Assessor:	T. Thiagarajan	Date & Time of Assessment:	31.01.2020 @ 1650hrs
NIMA Protocol:		1 st Inspection was done with the dismantling of hidden parts	
		1 st Inspection was done without the dismantling of hidden parts	
		2 nd Inspection was done where hidden damaged parts were dismantled in the presence of the Surveyor and not before	
	✓	2 nd Inspection was done where hidden damaged parts were dismantled not in the presence of the Surveyor	


L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748

AREA OF DAMAGED



Damage Consistency

YES

L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748

Damage Photographs



FULL VIEW



FULL VIEW

L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748



FULL VIEW



SPEEDOMETER

L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748



REAR BUMPER - DAMAGED



L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748



REAR BUMPER - DAMAGED



L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748



REAR BUMPER SENSOR - MALFUNCTION



L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748



REAR BUMPER SENSOR - MALFUNCTION



L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748



WORK IN PROGRESS



WORK IN PROGRESS

L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748



WORK IN PROGRESS



WORK IN PROGRESS

L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748

BEFORE PAINT



L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748




L.B.S. AUTO CONSULTANTS PTE LTD

Company Registration Number 200311321D

Correspondence Address: Block 8 Kensington Park Drive #01-07 Kensington Park Singapore 557323

Telephone: 65-62816690 Facsimile: 65-62818748





華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

NO. 1 KAKAI BUKIT AVENUE 6 #01-61/34 AUTOBAY@ KAKI BUKIT
SINGAPORE 409800
TEL: 67478054, 67465519 FAX: 67434896
Reg. No. 254578/00M

PART BY PART BILL FOR SJR 7374 L

VEHICLE NO : SJR 7374 L
MAKE/MODEL : HYUNDAI AVANTE
NAME : GOH KEE HUI DARON
ADDRESS : BLK 105 BEDOK RESERVOIR ROAD
#08-398
SINGAPORE 470105

DATE : 1-FEB-20

ACCIDENT DATE : 29-JAN-20

QTY	ITEM	AMOUNT (S\$)
-----	------	--------------

<u>LIST ITEMS</u>		
1 PC	BOOT LID	\$ 886.00
2 PCS	REAR TAILLAMPS	\$ 533.00
1 PC	REAR END PANEL	\$ 537.90
1 PC	REAR END PANEL INNER GARNISH	\$ 69.50
1 PC	REAR BUMPER	\$ 442.00
1 PC	REAR BUMPER REINFORCEMENT	\$ 262.00
2 PCS	REAR BUMPER REINFORCEMENT STAYS	\$ 134.80
		\$ 2,865.20
	Less 20.0%	\$ 573.04
		\$ 2,292.16

<u>SPECIAL NETT ITEMS</u>		
1 PC	REAR REVERSE SENSOR (1 SET)	\$ 280.00
		\$ 280.00

<u>S/No.</u>	<u>LABOUR</u>	
1	TO CHECK WIRING.	\$ 40.00
2	TO REMOVE AND REFIT INNER GARNISHES.	\$ 80.00
3	TO REMOVE AND REFIT REVERSE SENSOR.	\$ 80.00
4	PANEL BEATING	\$ 660.00
5	SPRAY PAINTING	\$ 880.00
6	TO UNDERSEAL	\$ 90.00
		\$ 1,830.00

TOTAL : \$ 4,402.16

SDLS: FOUR THOUSAND FOUR HUNDRED TWO AND CENTS SIXTEEN ONLY