

Date: 23.10.2020
Vehicle No: SMS426B
Model: HONDA FIT 1.3A
Chassis: GK31352957
Reg.Year: 2020

Third Party Insurer: MS 1ST CAP
Third Party Veh No: SHA4746E
Date of Accident: 17.10.2020

Not Authorised
Resurvey B4 again 2 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	HT/LM	\$756.00 ✓
2	FRONT LOWER GRILLE	1	HT	\$199.50 X
3	FRONT FOG LAMP COVER LH	1	HT/LM	\$42.00 ✓
4	FRONT FENDER INNER SHIELD LH	1	SM	\$105.00 X
5	FRONT SIDE RETAINER LH	1	DIR	\$12.60 ✓
6	HEADLAMP BRACKET LH	1		\$42.00 ?
7	SUPPORT PANEL	1	HT	\$588.00 X
SUB TOTAL				\$1,745.10
LESS 20%				-\$349.02
PARTS TOTAL				\$1,396.08

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRONT ACCIDENT AREA.

\$400.00 200l

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS.

\$400.00 220l

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$150.00 15l

TO APPLY ANTI-RUST COATING TO AFFECTED AREA.

HT \$100.00 X

LABOUR TOTAL \$1,050.00

TOTAL \$2,446.08

Vic

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

