

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS20011667/UQF3E2

Date: 03/11/2020

### REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No : SGJ4732J

Insured Vehicle No :

SKE9731H

Date of Loss: 23/10/2020

Nature of Claim:

TP

Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGJ4732J**

Make &amp; Model: TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No: 3ZZ4580957

Reg. Date: 12/07/2006 (Man. Year: 2006)

Chassis No: MR053ZEC107123917

Colour: Beige

Odometer: 129377 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/70 R14

Rear Tyre Size:

185/70 R14

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,227.01	1,183.51	43.50	3.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,855.00	1,280.00	575.00	31.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,082.01</b>	<b>2,463.51</b>	<b>618.50</b>	<b>20.07</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,900.00</b>		
<b>(\$\$)</b>	3,082.01	1,900.00	1,182.01	38.35
<b>+ GST 7.00/7.00% (\$\$)</b>	215.74	133.00	82.74	38.35
<b>Nett Amount (\$\$)</b>	<b>3,297.75</b>	<b>2,033.00</b>	<b>1,264.75</b>	<b>38.35</b>

### INSPECTION

Date of Assignment: 27/10/2020

Date Inspected: 28/10/2020 Inspected At:

NPH Auto Service (HQ)

Blk 9005 Tampines Steet 93, #01-246/254

Singapore 528839

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2020)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGJ4732J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR PROTECTOR	Scratched/Necessary	40.00 FL	*40.00 FL
2	1		*FRONT DOOR CHROME MOULDING	Necessary	25.00 FL	*25.00 FL
3	1		*REAR DOOR PROTECTOR	Scratched/Necessary	35.00 FL	*35.00 FL
4	1		*REAR DOOR CHROME MOULDING	Necessary	23.02 FL	*23.02 FL
5	1		*REAR DOOR RH	Bent/Warped	1,060.00 FL	*1,060.00 FL
6	1		*REAR DOOR W/STRIP RUBBER	Not Necessary	58.00 FL	*- FL
7	1		*REAR BUMPER	Torn	395.00 FL	*395.00 FL
					<b>Sub Total (S\$)</b>	<b>1,636.02</b>
					<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>409.01</b>
					<b>Total Parts (S\$)</b>	<b>1,227.01</b>
						<b>1,183.51</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	REMOVE & INSTALL R/DOOR,R/BUMPER,KNOCK F/DOOR,R/FENDER,WHEEL ARCH PANEL AND RESTRAIGHTEN BODY & CHASSIS	New	750.00	400.00
2	SPRAY PAINTING	New	1,000.00	800.00
3	CHECK WIRING SYSTEM	New	25.00	20.00
4	REMOVE & INSTALL REAR BOOT CARPET	New	80.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>1,855.00</b>	<b>1,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >