



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC20011671/Kcf3e2 Date: 25/08/2021 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	GBB 5815Z	
	Policy No. Z/20/VC06/105804	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	3,100.00	
	Assign From KENNY LIM	Assign Date	27/10/2020	
2. Vehicle Particulars & Condition				
	Make & Model TOYOTA DYNA (A)	c.c	2982	
	Engine No. HIDDEN	Year of Reg.	2009	
	Chassis No. JTFAT35Y60K200615	Colour	SILVER	
	Odometer 629657 KM	Steering	JAMMED	
	Brakes IN ORDER	Modification	NIL	
	General GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	GREEN MAX	8 mm
	L/H Front Tyre	195 R15X8	GREEN MAX	8 mm
	R/H Rear Tyre	155 R12X8 (D)	FALKEN	1/1 mm
	L/H Rear Tyre	155 R12X8 (D)	FALKEN	2/2 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 21/10/2020	Inspection Date	27/10/2020	
	Survey held at K KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
	A)THE MARKET VALUE IS S\$24,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	