

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd  
300 Beach Road  
#17-04/07 The Concourse  
Singapore 199555

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Kenny Lim

Date: 27 Oct 2020

## **Preliminary Advice**

Vehicle No	: GBB5815Z	Accident Date	: 21/10/2020
Make	: TOYOTA DYNA 150 MANUAL 3SEATER	Policy No.	: Z/20/VC06/105804
Assignment Date	: 27/10/2020	Excess	: S\$3,100.00
Date of Inspection	: 27/10/2020	Est. Duration of Repair	: 12
Inspection At	: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,379.25
Revised Amount	:S\$	10,701.50
Check Items (Estimated)	:S\$	10,548.00
Total	:S\$	21,249.50

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	24,000.00 (inclusive canopy)
COE / PARF Rebate	:S\$	10,292.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,708.00

### **Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Repairer able to undertake the repair cost not exceeding \$13,000.00 on lump sum basis.