

(08/11/13) wef
ASS. REC. BY: Marcus

REF:


CS/TP20011672/U+3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLH3401Y
at Workshop m/s Blue
of _____
Insured: SMP 2632M
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 465
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA LPR Seen: ✓ Consistent? : Yes or No
Est. Repairs: 9 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH3401Y Yr Regn: 31/10/16
Type: M.Csr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CAI
Make: maxda S c.c. 1998
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 50465 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JM6CW107160124637
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/55-R16
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 3 mm L/Bal. 6 mm
D.O.A. 24/10/20 D.O.I. 28/10/20
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Ajax</u>
	<u>NMC LIA 5012/ Dep 916</u>
	<u>Nett 14879</u>
	<u>1/5 @ 8020 RED:8815.3;52%)</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

<input type="checkbox"/> : Site Insp (\$ _____)	<input type="checkbox"/> : S + RS, SI
<input type="checkbox"/> : Interview (\$ _____)	<input type="checkbox"/> : Photos
<input type="checkbox"/> : Tech. Invs (\$ _____)	<input type="checkbox"/> : Others
<input type="checkbox"/> : Weekend (\$ _____)	

Report Format : _____

Lump Sum / I.B.I.: (\$ _____)

TOTAL

BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 KAKI BUKIT AVE 6 # 01-28/55
SINGAPORE 417883

not Authorized
2/2/20
1/s \$8000 Phys

VEHICLE No :SLH 3401Y

1PC	TAILGATE	Body ID	\$1,637.00	✓
1PC	TAILGATE REAR WINDSCREEN	11	\$1,125.40	X
1PC	TAILGATE REAR WINDSCREEN MOULDING	neu	\$80.50	✓
1PC	TAILGATE REAR LOGO	neu	\$65.00	✓
1PC	TAILGATE 'MAZDA' EMBLEM	neu	\$49.50	✓
1PC	TAILGATE 'SKYACTIVE' EMBLEM	neu	\$80.00	✓
1PC	TAILGATE 'S' EMBLEM	neu	\$32.60	✓
1PC	TAILGATE INNER LOCK	DD/shorted	\$256.50	✓
1PC	TAILGATE INNER TRIM	De/cro	\$421.60	✓
2PCS	TAILGATE REFLECTORS @\$409.40	11	\$818.80	X
1PC	TAILGATE WEATHERSTRIP	twi	\$177.50	✓
2PCS	TAILLAMPS @\$601.20	11	\$1,202.40	X
1PC	REAR BUMPER	Dis	\$961.20	✓
2PCS	REAR BUMPER SIDE RETAINERS @\$35.00	N/S Bent	\$70.00	1PC
1PC	REAR BUMPER REFLECTOR N/S	cne	\$53.00	✓
1PC	REAR BUMPER REINFORCEMENT	Bent	\$155.40	✓
1PC	REAR BUMPER SPLASH SHIELD N/S	Torn	\$81.50	✓
1PC	REAR END PANEL	Body ID	\$515.70	✓
1PC	REAR END PANEL TOP GARNISH	twi	\$121.60	✓
1PC	REAR FLOOR PANEL	crumpled / suc	\$1,245.50	✓
1PC	REAR FLOOR PANEL TOOLS TRAY	cng	\$425.90	✓
1PC	REAR FLOOR PANEL TOP BOARD	11	\$511.20	X
1PC	REAR FENDER INNER TRIM BOARD N/S	De/cne	\$380.50	✓
1PC	REAR EXHAUST	Bent	\$991.80	✓
1PC	REAR EXHAUST HEAT SHIELD	Dis	\$145.20	✓
1PC	REAR EXHAUST CHROME PIPE N/S	Bent	\$80.00	✓
			\$11,685.30	

(20%)

7992.50
6394

S.NETT			
1SET	REAR BUMPER REVERSE SENSOR	short	\$280.00 200
1SET	REAR BUMPER CLIPS	neu	\$40.00 ✓
1PC	REAR END PANEL SEALANT	neu	\$50.00 ✓
1PC	REAR WINDSCREEN SEALANT	neu	\$50.00 40
1PC	REAR WINDSCREEN INNER SEAL	neu	\$30.00 ✓
1PC	REAR LICENCE PLATE W/HOLDER	Bent	\$50.00 40
1SET	REAR REVERSE CAMERA	su	\$380.00 X

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	100
TO DISMANTLE & REFIX PETROL TANK	\$100.00	60

TO TRANSFER TAILGATE MECHANISM
TO DISMANTLE & REPLACED REAR EXHAUST
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$100.00	60
	\$100.00	60
	\$120.00	100
	\$1,800.00	1400
	\$1,600.00	1280
TOTAL	\$16,815.30	

10054

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: