

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20011673/QPA3Q2
Date: 16/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900086330
Claimant Vehicle No :	SMB1558L	Insured Vehicle No :	GBJ3778T
Date of Loss:	19/10/2020	Nature of Claim:	TP
		Claim No:	8217162229SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB1558L		
Make & Model:	MAN NL320F (A22), 10.5 D ABS TURBO (A)	Engine No:	50339001473910
Reg. Date:	23/12/2014 (Man. Year: 2014)	Chassis No:	WMAA22ZZ8F7002514
Colour:	Multi-colour	Odometer:	532448 km
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,823.56	12,308.45	12,515.11	50.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,262.00	3,092.00	170.00	5.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,085.56	15,400.45	12,685.11	45.17
Approved Total (Overridden) (S\$)		12,950.00		

Nett Amount (S\$)	28,085.56	12,950.00	15,135.56	53.89
+ Loss of Use (5.0 x S\$250.00/day) (S\$)		1,250.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		14,207.00		

INSPECTION

Date of Assignment: 26/10/2020

Date Inspected: 26/10/2020

Estimated Period of Repair: 5.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: OI SUN PIN**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*LAMP ,STOP :LED (MAN BUS)	Crumpled	2,283.40 F	*2,283.40 FL
2	1		*LAMP,INDICATOR:LED (MAN BUS)	Crumpled	1,274.10 F	*1,274.10 FL
3	1		*LAMP ,REVERSE (MAN BUS)	Crumpled	77.60 F	*77.60 FL
4	1		*REFLECTOR ,TRIM:FOR MAN BUS	Cracked	77.60 F	*77.60 FL
5	1		*PANEL,REFLECTOR:REAR ,RH,FOR MAN BUS	Crumpled	107.00 F	*107.00 FL
6	1		*DOOR :ENGINE ,REAR,FOR MAN A22 BUS	Repair	1,868.80 F	*- FL
7	1		*COVER :REAR TAIL LAMP ,RH,FOR MAN A22 BUS	Crumpled	974.70 F	*974.70 FL
8	1		*BUMPER:REAR ,CENTRE ,FOR MAN A22 BUS	Repair	1,868.80 F	*- FL
9	1		*BRACKET,ATTACHMENT:FOR MAN A22 BUS	Repair	569.30 F	*- FL
10	1		*PANEL,SIDE:R11,FOR MAN A22 BUS	Repair	1,782.50 F	*- FL
11	1		*PANEL ,SIDE:R10,FOR MAN A22 BUS	Repair	192.70 F	*- FL
12	1		*PANE,SIDE:R9 WITH FRAME ,FOR MAN A22 BUS	Repair	710.70 F	*- FL
13	1		*LOCK ,LEVER LATCH :WITH KEY ,FOR MAN A22	Jammed	27.50 F	*27.50 FL
14	1		*STICKER SG LOVE	Necessary	75.00 FS	*75.00 FS
15	1		*STICKER SMRT	Necessary	75.00 FS	*75.00 FS
16	1		*STICKER 60KM/H	Necessary	5.00 FS	*5.00 FS
17	2		*PAR RUBBER	Serviceable	271.38 F	*- FL
18	1		*FAN BLADE	Serviceable	886.50 F	*- FL
19	1		*COOLANT:20 LTRS/PAIL ,ANTIFREEZE MAN BUS	Necessary	262.50 F	*262.50 FL
20	1		*HYDRAULIC TANK	Broken	1,548.90 F	*1,548.90 FL
21	1		*FAN HUB	Serviceable	683.80 F	*- FL
22	1		*FAN CARRIER	Repair	2,330.25 F	*- FL
23	1		*PIPE,HOSE:N1-10NNX880,FOR MAN A22	Broken	291.18 F	*291.18 FL
24	1		*PIPE,HOSE:N1-10NNX400,FOR MAN A22	Broken	97.50 F	*97.50 FL
25	2		*PAD:RUBBER,M8X21X9,5,FOR MAN A22 BUS	Crumpled	214.00 F	*214.00 FL
26	1		*HOSE:FOR HYDRAULIC FAN MOTOR ,MAN A22 BUS	Broken	767.85 F	*767.85 FL
27	1		*MOTOR FAN :FOR MAN A22 BUS	Jammed	5,500.00 F	*5,500.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	24,823.56	13,658.83
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	1,350.38
Total Parts (\$)	24,823.56	12,308.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	2,120.00	2,120.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	942.00	772.00
3	TOWING CHARGE	New	200.00	200.00
Gross Labour Cost (\$\$)			3,262.00	3,092.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >