



## Section A - Accident Details

Registration Number	SHC4456G
Case Reference Number	TAX/10/20/2047
Registration Date	4/3/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	WONG KOK KEE
Type of Accident	Head to Rear
Accident Date and Time	23/10/2020 6:50 AM
Accident Reported Date and Time	24/10/2020 10:50 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108572
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	26/10/2020 8:44 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$1,656.00	\$200.00
Total Spare Part Cost	\$3,009.98	\$782.44
Total Other Cost	\$660.00	\$50.00
<b>TOTAL COST</b>	<b>\$6,001.98</b>	<b>\$1,232.44</b>
Lump Sum Total	\$6,000.00	\$1,250.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / EQ
ARC / Surveyor Sign Off Date	26/10/2020 2:44 PM	26/10/2020 2:31 PM
Signature		
Remarks		L/S, After paint photo.

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2011-0054	Invoice Number	
Quotation Date	05.11.2020	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BATTERY PANEL	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,656.00	\$200.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$660.00	\$50.00

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check ✗
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check ✗
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check ✗
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check ✗
		76891-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check ✗
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check ✗
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given ✗
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check ✗

		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X
	64730-47031B2	PANEL ASSY. DECK RH	0.00	\$307.00	0.00	\$0.00	Replace	Not Given X
		BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Not Given X
	74481-47050	BATTERY CLAMP	0.00	\$16.10	0.00	\$0.00	Replace	Not Given X
	74440-47030	BATTERY TRAY	0.00	\$42.80	0.00	\$0.00	Replace	Not Given X
	52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Not Given X
	81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace ✓
	61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Not Given X
	61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given X
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X
		STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given X
	65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given X
	58302-47030	FLOOR PANEL RR/RH	0.00	\$209.90	0.00	\$0.00	Replace	Not Given X
	62940-16060	DUCT ASSY. QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Check X
Total				\$4,712.81		\$978.05		

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

978.05

- 20%

782.44

+ 200.00

+ 250.00

1232.44

4/5 \$1250/-