

## Section A - Accident Details

|                                    |                     |
|------------------------------------|---------------------|
| Registration Number                | SHC4456G            |
| Case Reference Number              | TAX/10/20/2047      |
| Registration Date                  | 4/3/2016            |
| Company Type                       | SMRT Taxis Pte Ltd  |
| Make                               | TOYOTA              |
| Model                              | PRIUS               |
| Name of Driver                     | WONG KOK KEE        |
| Type of Accident                   | Head to Rear        |
| Accident Date and Time             | 23/10/2020 6:50 AM  |
| Accident Reported Date and Time    | 24/10/2020 10:50 AM |
| Is Surveyor Required?              | Yes                 |
| Survey by                          |                     |
| Vehicle is Towed Back?             | No                  |
| Towed Back Date and Time           |                     |
| Replacement Vehicle issued?        | No                  |
| Job Card Number                    | 24108572            |
| Special Instruction to ARC, if any | REAR PORTION        |
| Prepared Date and Time             | 26/10/2020 8:44 AM  |
| Chassis Number                     |                     |
| Mileage                            |                     |
| Work Shop                          |                     |
| Repair Completion Date and Time    |                     |

## Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |                                                                                     |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost            | \$676.00                                                                            | \$200.00                                                                            |
| Total Spray Cost             | \$1,656.00                                                                          | \$200.00                                                                            |
| Total Spare Part Cost        | \$3,009.98                                                                          | \$782.44                                                                            |
| Total Other Cost             | \$660.00                                                                            | \$50.00                                                                             |
| <b>TOTAL COST</b>            | <b>\$6,001.98</b>                                                                   | <b>\$1,232.44</b>                                                                   |
| Lump Sum Total               | \$6,000.00                                                                          | \$1,250.00 (L/S)                                                                    |
| Number of Repair Days        | 5.0                                                                                 | 3.0                                                                                 |
| Prepared / Adjusted By       | Tuck Foo Kok                                                                        | Sun Pin (LKK) / EQ                                                                  |
| ARC / Surveyor Sign Off Date | 26/10/2020 2:44 PM                                                                  | 26/10/2020 2:31 PM                                                                  |
| Signature                    |  |  |
| Remarks                      |                                                                                     | L/S, After paint photo.                                                             |

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-2011-0054 | Invoice Number |  |
| Quotation Date   | 05.11.2020   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope              | Quotation from AR | Adjusted by Surveyor, if applicable |
|------------------------|-------------------|-------------------------------------|
| TO REPAIR REAR PORTION | \$676.00          | \$200.00 /                          |
| <b>Total Labour</b>    | <b>\$676.00</b>   | <b>\$200.00</b>                     |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY REAR BUMPER                          | \$378.00           | \$200.00 /                          |
| TO RESPRAY BUMPER BEAM                          | \$180.00           | \$0.00                              |
| TO RESPRAY REAR PANEL                           | \$180.00           | \$0.00                              |
| TO RESPRAY BATTERY PANEL                        | \$180.00           | \$0.00                              |
| TO RESPRAY REAR FLOOR SIDE PANEL RH             | \$180.00           | \$0.00                              |
| TO RESPRAY REAR FENDER RH                       | \$378.00           | \$0.00                              |
| TO RESPRAY TROUGH BACK DOOR RH                  | \$180.00           | \$0.00                              |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$1,656.00</b>  | <b>\$200.00</b>                     |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                                                           | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---------------------------------------------------------------------|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION                                 | \$80.00            | \$20.00 /                           |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                             | \$100.00           | \$30.00 /                           |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR | \$120.00           | \$0.00                              |
| TO REMOVE AND REFIT WIRE HARDESS                                    | \$200.00           | \$0.00                              |
| TO REPLACE SUNDRY PARTS                                             | \$100.00           | \$0.00                              |
| TO WASH AND VACUUM                                                  | \$60.00            | \$0.00                              |
| <b>Total Other Costs</b>                                            | <b>\$660.00</b>    | <b>\$50.00</b>                      |

## Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name                  | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|----------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 52159-47905  | BUMPER REAR                | 1.00     | \$458.60        | 25.00        | \$343.95         | Replace            | Replace           |
|             |         | 52161-16010  | BUMPER CLIPS               | 10.00    | \$1.61          | 25.00        | \$12.08          | Replace            | Replace           |
|             |         | 52023-12240  | BUMPER REINFORCEMENT REAR  | 0.00     | \$205.70        | 0.00         | \$0.00           | Replace            | Check X           |
|             |         | 52016-47030  | ARM SUB-ASSY, RR BUMPER LH | 0.00     | \$139.60        | 0.00         | \$0.00           | Replace            | Check X           |
|             |         | 52015-47050  | ARM SUB-ASSY, RR BUMPER RH | 0.00     | \$139.60        | 0.00         | \$0.00           | Replace            | Check X           |
|             |         |              | PIXEL STICKER              | 2.00     | \$60.00         | 0.00         | \$120.00         | Replace            | Replace           |
|             |         | 76087-47020  | BUMPER LIP COVER RR/RH     | 0.00     | \$118.10        | 0.00         | \$0.00           | Replace            | Check X           |
|             |         | 76891-47020  | BUMPER LIP REAR            | 0.00     | \$228.90        | 0.00         | \$0.00           | Replace            | Check X           |
|             |         | 52591-47021  | BUMPER SEAL, RR RH         | 0.00     | \$65.70         | 0.00         | \$0.00           | Replace            | Check X           |
|             |         | 52575-47020  | BUMPER SIDE RETAINER RR/RH | 0.00     | \$94.80         | 0.00         | \$0.00           | Replace            | Not Given X       |
|             |         | 58307-47060  | END PANEL                  | 0.00     | \$602.10        | 0.00         | \$0.00           | Replace            | Check X           |

CR4  
NRC  
SVC  
SVC  
SVC  
SVC  
NRC  
SVC  
SVC  
SVC  
SVC  
SVC

|       |               |                         |      |            |       |          |         |           |   |
|-------|---------------|-------------------------|------|------------|-------|----------|---------|-----------|---|
|       |               | SEALANT SIKAFLEX        | 0.00 | \$37.00    | 0.00  | \$0.00   | Replace | Not Given | X |
|       | 64730-47031B2 | PANEL ASSY. DECK RH     | 0.00 | \$307.00   | 0.00  | \$0.00   | Replace | Not Given | X |
|       |               | BATTERY                 | 0.00 | \$278.00   | 0.00  | \$0.00   | Replace | Not Given | X |
|       | 74481-47050   | BATTERY CLAMP           | 0.00 | \$16.10    | 0.00  | \$0.00   | Replace | Not Given | X |
|       | 74440-47030   | BATTERY TRAY            | 0.00 | \$42.80    | 0.00  | \$0.00   | Replace | Not Given | X |
|       | 52562-47010   | TAIL LAMP BRACKET, RH   | 0.00 | \$30.70    | 0.00  | \$0.00   | Replace | Not Given | X |
|       | 81551-47180   | TAIL LAMP RH            | 1.00 | \$557.80   | 10.00 | \$502.02 | Replace | Replace   | X |
|       | 61621-47030   | TROUGH, BACK DOOR       | 0.00 | \$110.90   | 0.00  | \$0.00   | Replace | Not Given | X |
|       | 61604-47090   | FENDER RR/RH            | 0.00 | \$766.80   | 0.00  | \$0.00   | Replace | Not Given | X |
|       |               | SMRT LOGO               | 0.00 | \$7.80     | 0.00  | \$0.00   | Replace | Not Given | X |
|       |               | STICKER DECAL 6555 8888 | 0.00 | \$21.60    | 0.00  | \$0.00   | Replace | Not Given | X |
|       | 65637-47021   | FENDER LINER RR/RH      | 0.00 | \$141.30   | 0.00  | \$0.00   | Replace | Not Given | X |
|       | 58302-47030   | FLOOR PANEL RR/RH       | 0.00 | \$209.90   | 0.00  | \$0.00   | Replace | Not Given | X |
|       | 62940-16060   | DUCT ASSY. QUARTER      | 0.00 | \$70.40    | 0.00  | \$0.00   | Replace | Check     | X |
| Total |               |                         |      | \$4,712.81 |       | \$978.05 |         |           |   |

SVC  
SVC  
SVC  
SVC  
SVC  
SVC  
CRA  
SVC  
SVC  
SVC  
SVC  
SVC  
SVC  
SVC

## Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Total       |         |              |           |          |               |              |                  |           |                |

978.05 /

- 20%

782.44 /

+ 200.00 /

+ 250.00 /

1232.44 /

4/5 \$1250/- /

3 days