

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20011675/GQF3E2

Date: 19/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : FR7886Z

Insured Vehicle No : SHB4111G

Date of Loss: 02/10/2020

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FR7886Z

Make & Model: HONDA CBR600F, 599cc (M)

Engine No: PC35E2102630

Reg. Date: 20/01/2000 (Man. Year: 1999)

Chassis No: JH2PC35A8YM102005

Colour: Red

Odometer: 116402 km

Engine Capacity: 599 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-17

Rear Tyre Size: 180/55-17

Front Left Side: Timsun 4 mm

Rear Left Side: Timsun 4 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,075.00	3,859.50	1,215.50	23.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	230.00	500.00	68.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,805.00	4,089.50	1,715.50	29.55
Approved Total (Overridden) (S\$)		3,250.00		
Nett Amount (S\$)	5,805.00	3,250.00	2,555.00	44.01

INSPECTION

Date of Assignment: 27/10/2020

Date Inspected: 27/10/2020

Inspected At:

Yp Motorsports Trading (HQ)
Blk 9004 Tampines St 93, #01-92
Singapore 528836

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Apr 2021)	
Parts:	N/A	HONDA CBR600F 599cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FR7886Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	180.00 FL	*180.00 FL
2	1		*RIGHT MIRROR	Missing	65.00 FL	*65.00 FL
3	1		*LEFT MIRROR	Cut	65.00 FL	*65.00 FL
4	1		*CLUTCH LEVEL	Broken	50.00 FL	*50.00 FL
5	1		*TOP CROWING	Cracked	280.00 FL	*280.00 FL
6	1		*HEAD LAMP	Broken	420.00 FL	*420.00 FL
7	1		*PAIR THROTTLE CABLE	Not Necessary	95.00 FL	*- FL
8	1		*PAIR BAR END	Cut	75.00 FL	*75.00 FL
9	1		*FUEL TANK	Dented	980.00 FL	*980.00 FL
10	1		*AIR INTAKE COVER (R/H)	Cut	60.00 FL	*60.00 FL
11	1		*ENGINE COVER (L/H)	Cut	180.00 FL	*180.00 FL
12	1		*LOWER FAIRING (R/H)	Not Necessary	150.00 FL	*- FL
13	1		*LOWER FAIRING (L/H)	Not Necessary	150.00 FL	*- FL
14	1		*TAIL CROWING	Cut	320.00 FL	*320.00 FL
15	1		*SET BREMO 19RCS BRAKE MASTER PUMP	Cut	480.00 FS	*480.00 FS
16	1		*SET FRONT BRAKE HOSE	Not Necessary	180.00 FS	*- FS
17	1		*GIVI BOX (48L)	Cut	280.00 FS	*250.00 FS
18	1		*SET FRAME SLIDER	Distorted	80.00 FS	*60.00 FS
19	1		*SET MORIWAKI ABBSAY (FOOT REST & GEAR SHIFT ASSY)	Cut	1,200.00 FS	*600.00 FS
20	1		*ENGINE COVER GASKET	Necessary	12.00 FS	*12.00 FS
21	4		*L ENGINE OIL	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,382.00	4,127.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	307.00	267.50
Total Parts (\$\$)	5,075.00	3,859.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	30.00
2	FRONT FORK & WHEEL ALIGNMENT	New	180.00	0.00
3	LABOUR CHARGE TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, INCLUDING REPAIRING, RE-FIXING, ADJUSTING, CHECKING, ETC	New	500.00	200.00
Gross Labour Cost (\$\$)			730.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >