

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0799/2020/NS
DATE	:	26-Oct-20
WIP	:	53995

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

Xiao Chen.
\$18233.56
13 Days.

OWNER'S NAME	:	MR LOW KWOK SHION, KENNETH (LIU GUOXIONG, KENNETH)
ADDRESS	:	33 HONG SAN WALK SINGAPORE 689024
TELEPHONE	:	HP +65 97632486
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1800129363-01
VEHICLE NO	:	SJS 986 L
MODEL CODE	:	AUDI A3 SEDAN 1.4 TFSI CO
MODEL YEAR	:	30/10/2018
ENGINE NO	:	CZE 846206
CHASSIS NO	:	WAUZZZ8V2K1003106
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	18-Oct-20
PLACE OF ACCIDENT	:	PLAZA SINGAPURA CARPARK



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJS 986 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 280.00	✓
2	TO RENEW 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00	✓
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$ 400.00	✓
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$ 200.00	150 ✓
5	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	✓
SUB TOTAL LABOUR CHARGES		: \$ 1,760.00	

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJS 986 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00 ✓	✓
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00 ✓	✓
8	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00 ✓	3500 ✓
9	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 5,750.00 ✓	3025 ✓ 5.5 x 550 = 3025 ✓
10	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓	✓
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 16,382.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 986 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 REAR BUMPER <i>Repis</i>	\$	1,944.00	+	
2 REAR BUMPER FIXING PARTS <i>new</i>	\$	191.00	+	
3 WHEEL HOUSING LINER ADAPTER - RH <i>3 new</i>	\$	37.00	+	
4 REAR BUMPER GUIDE SECTION - RH	\$	66.00	+	
5 REAR FENDER - RH <i>Dented</i>	\$	2,305.00	✓	1844
6 REAR WINDSCREEN <i>3 new</i>	\$	805.00	✓	643.6
7 SIDE WINDOW - RH	\$	563.00	✓	450.40
8 PRIMER <i>new</i>	\$	19.00	✓	14.96
9 WHEEL HOUSING LINER - RH <i>new</i>	\$	237.00	+	
10 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	88.00	+	
11 REAR DOOR - RH <i>Dented</i>	\$	2,494.00	✓	1995.20
12 REAR DOOR OUTER SEAL - RH <i>NEC</i>	NEC \$	159.00	✓	126.80
13 BONDING AGENT <i>Not NEC</i>	NEC \$	47.00	?	×
14 CLEANING SOLUTION <i>Not NEC</i>	NEC \$	65.00	?	×
15 REAR DOOR ATTACHMENT PARTS <i>new</i>	\$	127.00	+	
16 REAR DOOR CATCH <i>Not NEC</i>	\$	93.00	?	×
17 REAR ALUMINIUM RIM - RH <i>cut</i>	\$	699.00	✓	558.80
18 REAR WHEEL SPOILER - RH <i>Not new</i>	\$	35.00	+	
19 1/4 GLASS SEALANT <i>3 new</i>	S/N \$	100.00	✓	✓
20 REAR WINDSCREEN SEALANT	S/N \$	200.00	✓	✓
SUB TOTAL SPARE PARTS	:	\$ 10,274.00		

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 986 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 METAL FILLER POWDER	S/N	\$	280.00	✓ ✓
22 STONE CHIP	S/N	\$	180.00	✓ ✓
23 CAVITY WAX	S/N	\$	140.00	✓ ✓
24 ACRYLIC SEALANT	S/N	\$	180.00	✓ ✓
25 SUNDRIES		\$	300.00	12.80 ✓
TOTAL SPARE PARTS		:	\$ 11,354.00	
TOTAL LABOUR CHARGES		:	\$ 16,382.00	
GRAND TOTAL		:	\$ 27,736.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian G
27/10/20

Not Authorised, 13 Days
H.S.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT