

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0799/2020/NS
DATE : 26-Oct-20
WIP : 53995

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

**13 days exclude .
jb 17 May 21**

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LOW KWOK SHION, KENNETH
(LIU GUOXIONG, KENNETH)
ADDRESS : 33 HONG SAN WALK
SINGAPORE 689024
TELEPHONE : HP +65 97632486
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800129363-01
VEHICLE NO : **SJS 986 L**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI CO
MODEL YEAR : 30/10/2018
ENGINE NO : CZE 846206
CHASSIS NO : WAUZZZ8V2K1003106
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Oct-20
PLACE OF ACCIDENT : PLAZA SINGAPURA CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJS 986 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	280.00	\$	280.00
2	TO RENEW 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL.	S/N \$	600.00	\$	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	\$	400.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	\$	150.00
5	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	280.00	\$	280.00
SUB TOTAL LABOUR CHARGES		:	\$ 1,760.00	\$	<u>1,710.00</u>

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJS 986 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>	<i>\$ 1,710.00</i>
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 1,400.00	<i>\$ 1,400.00</i>
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$ 1,400.00	<i>\$ 1,400.00</i>
8	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. CUT OUT AND WELD RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	<i>\$ 3,500.00</i>
9	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR ENTRANCES, RHS SILL PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	\$ 5,750.00	<i>\$ 3,025.00</i>
10	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	<i>\$ 280.00</i>
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	<i>\$ 192.00</i>
TOTAL LABOUR CHARGES		: \$ 16,382.00	<i>\$ 11,507.00</i>

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 986 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER		\$ 1,944.00	
2	REAR BUMPER FIXING PARTS		\$ 191.00	
3	WHEEL HOUSING LINER ADAPTER - RH		\$ 37.00	
4	REAR BUMPER GUIDE SECTION - RH		\$ 66.00	
5	REAR FENDER - RH		\$ 2,305.00	\$ 1,844.00
6	REAR WINDSCREEN		\$ 805.00	\$ 643.60
7	SIDE WINDOW - RH		\$ 563.00	\$ 450.40
8	PRIMER		\$ 19.00	\$ 14.96
9	WHEEL HOUSING LINER - RH		\$ 237.00	
10	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00	
11	REAR DOOR - RH		\$ 2,494.00	\$ 1,995.20
12	REAR DOOR OUTER SEAL - RH	NEC	\$ 159.00	\$ 126.80
13	BONDING AGENT	NEC	\$ 47.00	
14	CLEANING SOLUTION	NEC	\$ 65.00	
15	REAR DOOR ATTACHMENT PARTS		\$ 127.00	
16	REAR DOOR CATCH		\$ 93.00	
17	REAR ALUMINIUM RIM - RH		\$ 699.00	\$ 558.80
18	REAR WHEEL SPOILER - RH		\$ 35.00	
19	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
20	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
SUB TOTAL SPARE PARTS		:	\$ 10,274.00	\$ 5,933.76

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 986 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
			<i>c/f</i>
			\$ 5,933.76
21 METAL FILLER POWDER	S/N	\$ 280.00	\$ 280.00
22 STONE CHIP	S/N	\$ 180.00	\$ 180.00
23 CAVITY WAX	S/N	\$ 140.00	\$ 140.00
24 ACRYLIC SEALANT	S/N	\$ 180.00	\$ 180.00
25 SUNDRIES		\$ 300.00	\$ 12.80
TOTAL SPARE PARTS	:	\$ 11,354.00	\$ 6,726.56
TOTAL LABOUR CHARGES	:	\$ 16,382.00	\$ 11,507.00
GRAND TOTAL	:	\$ 27,736.00	\$ 18,233.56

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-17/05/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT