

**BIFROST AUTO PTE LTD**

## REPAIR ESTIMATE

DATE: 26-Oct-20

INSURANCE: *China T-ship*

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA 4847 Y

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>st</i>	1	\$950.50	\$950.50
INSULATOR, HOOD <i>HW</i>	1	\$398.10	\$398.10
INSULATOR CLIPS 10 PCS <i>HW</i>	1	\$36.80	\$36.80
BONNET CABLE <i>HW</i>	1	\$83.20	\$83.20
BONNET HINGE (RH) <i>HW</i>	1	\$87.70	\$87.70
BONNET HINGE (LH) <i>HW</i>	1	\$87.70	\$87.70
BONNET LOCK <i>st</i>	1	\$132.60	\$132.60
CATCH, HOOD AUXILIARY HOOK <i>HW</i>	1	\$8.60	\$8.60
RADIATOR GRILLE <i>broken</i>	1	\$438.00	\$438.00
RADIATOR GRILLE EMBLEM <i>HW</i>	1	\$88.00	\$88.00
FRONT BUMPER COVER <i>HW</i>	1	\$499.90	\$499.90
FRONT BUMPER REINFORCEMENT <i>st</i> <i>Decker</i>	1	\$696.40	\$696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>HW</i> <i>st</i>	1	\$115.70	\$115.70
FRONT BUMPER LOWER REINFORCEMENT <i>st</i>	1	\$364.20	\$364.20
FRONT BUMPER LOWER REINFORCEMENT BRACKET <i>HW</i> <i>st</i>	1	\$330.00	\$330.00
FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH) <i>HW</i>	2	\$ 320.70	\$641.40
FRONT SIDE MEMBER SIDE COVER <i>HW</i>	1	\$ 172.50	\$172.50
FRONT BUMPER SPONGE <i>HW</i>	1	\$78.80	\$78.80
FRONT BUMPER LOWER GRILLE <i>damaged mounting</i>	1	\$148.60	\$148.60
LAMP ASSY, FOG, RH <i>HW</i>	1	\$920.00	\$920.00
LAMP ASSY, FOG, LH <i>mainly crack</i>	1	\$920.00	\$920.00
FRONT BUMPER CLIPS <i>HW</i>	1	\$22.00	\$22.00
FRONT BUMPER SIDE RETAINER <i>HW</i> <i>broken</i>	1	\$77.00	\$77.00
FRONT LOWER PANEL <i>HW</i> <i>st</i>	1	\$320.65	\$320.65
FRONT LOWER SIDE RAIL (LH/RH) <i>HW</i>	2	\$230.80	\$461.60
FRONT LOWER CROSSMEMBER <i>HW</i>	1	\$357.70	\$357.70
FRONT UNDER COVER <i>HW</i>	1	\$180.80	\$180.80
ENGINE UNDER COVER (RR) <i>HW</i>	1	\$457.40	\$457.40
ENGINE UNDER COVER CENTER <i>HW</i>	1	\$523.40	\$523.40
FRONT BUMPER TOP GARNISH <i>HW</i>	1	\$225.40	\$225.40
COVER, FRONT BUMPER HOLE, RH <i>HW</i>	1	\$28.38	\$28.38
COVER, FRONT BUMPER HOLE, LH <i>HW</i>	1	\$28.38	\$28.38
ABSORBER, FRONT BUMPER, LOWER <i>mainly broken</i>	1	\$127.70	\$127.70
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>	1	\$3,455.00	\$3,455.00
HEADLAMP ECU <i>mainly broken</i>	1	\$682.60	\$682.60
HEAD LAMP PANEL (LH) <i>st</i>	1	\$240.10	\$240.10
TOP PANEL CENTRE <i>st</i>	1	\$364.98	\$364.98
TOP PANEL SIDE <i>st</i>	1	\$145.90	\$145.90
BRACE PANEL <i>HW</i>	1	\$75.20	\$75.20
RADIATOR ASSY <i>st</i> <i>mainly broken</i>	1	\$1,841.80	\$1,841.80
RADIATOR FAN GRILLE <i>HW</i>	1	\$632.40	\$632.40

COOLANT <i>HL</i>		1	\$45.00	\$45.00	X
DEFLECTOR, RADIATOR SIDE, LH <i>SVL</i>		1	\$83.50	\$83.50	X
RADIATOR BOTTOM MOUNTING <i>HL</i>		1	\$27.50	\$27.50	X
STAY, RADIATOR SUPPORT, LH <i>HL</i>		1	\$65.70	\$65.70	X
RADIATOR FAN BLADE (LH) <i>HL</i>		1	\$233.10	\$233.10	X
RADIATOR FAN MOTOR (LH) <i>HL</i>		1	\$543.70	\$543.70	X
RADIATOR FAN COWLING (LH/RH) <i>HL</i>		1	\$451.30	\$451.30	X
CONDENSER ASSY, W/RECEIVER <i>2 Rst</i>		1	\$1,336.60	\$1,336.60	✓
FENDER SUB-ASSY, FRONT LH <i>Revised</i>		1	\$945.30	\$945.30	✓
FRONT HOUSING ASSY <i>leg</i>		1	\$945.26	\$945.26	X
FRONT FENDER SHIELD <i>form</i>		1	\$198.50	\$198.50	✓
FRONT FENDER SHIELD CLIP <i>HL</i>		1	\$14.90	\$14.90	✓
FRONT FENDER HYBRID EMBLEM, LH <i>HL</i>		1	\$86.50	\$86.50	✓
BRACKET, FRONT SIDE PANEL, LH <i>HL Rst</i>		1	\$86.30	\$86.30	X
TRAY, BATTERY <i>HL defunct HL</i>		1	\$42.80	\$42.80	X
<b>SUB TOTAL</b>				<b>\$22,553.05</b>	
<b>LESS 20% 25%</b>				<b>\$4,510.61</b>	
<b>DISCOUNTED TOTAL</b>				<b>\$18,042.44</b>	
FRONT NO. PLATE <i>cut</i>	SN	1	\$25.00	\$25.00	} 45/-
FRONT NO. PLATE TRIM COVER <i>broken</i>	SN	1	\$30.00	\$30.00	
FRONT NO. PLATE GARNISH <i>defunct</i>	SN	1	\$99.00	\$99.00	
FRONT BUMPER LOGO <i>HL</i>	SN	1	\$87.10	\$87.10	
<b>SUB TOTAL</b>				<b>\$241.10</b>	
<b>Labour Charge</b>					
Panel Beating		1	\$1,600.00	\$1,600.00	800/-
Spray Painting Charge		1	\$1,400.00	\$1,400.00	700/-
Wiring Charge		1	\$180.00	\$180.00	30/-
Tuff Kote		1	\$160.00	\$160.00	40/-
Towing Charge		1	\$80.00	\$80.00	HL
Remove/Refix Radiator		1	\$90.00	\$90.00	50/-
Remove/Refix Aircon & Refill Gas		1	\$130.00	\$130.00	80/-
Remove/Refix Fuse Box		1	\$120.00	\$120.00	HL
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	150/-
<b>TOTAL LABOUR</b>				<b>\$4,310.00</b>	
<b>ESTIMATE TOTAL</b>				<b>\$22,593.54</b>	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

28/10/2020 C.H. 1000hrs

HL Arthur

6 days.

LKK Auto

# BIFROST AUTO PTE LTD

## REPAIR SUPPLEMENTARY

DATE: 2-Nov-20

INSURANCE: China Teoping.

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA 4847 Y (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
UNIT ASSY, HEADLAMP, RH (LED) <i>mainly broken</i>	1	\$3,455.00	\$3,455.00
HEAD LAMP PANEL (RH) <i>1st</i>	1	\$240.10	\$240.10
TOP PANEL SIDE <i>1st</i>	1	\$145.90	\$145.90
BATTERY <i>disturb/damaged 50% SH</i> SN	1	\$220.00	\$220.00
SUB TOTAL			\$4,061.00
LESS 20% <i>25%</i>			\$812.20
DISCOUNTED TOTAL			\$3,248.80
SUB TOTAL			\$0.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*1 yan*  
*2 Kk Auto*

*8*