

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 26-Oct-20

INSURANCE: China Taiping

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHA 4847 Y

CC6/CTI20011684/Dr3

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET <i>st</i>	1	\$950.50	\$950.50
INSULATOR, HOOD <i>HH</i>	1	\$398.10	\$398.10
INSULATOR CLIPS 10 PCS <i>HH</i>	1	\$36.80	\$36.80
BONNET CABLE <i>HH</i>	1	\$83.20	\$83.20
BONNET HINGE (RH) <i>HH</i>	1	\$87.70	\$87.70
BONNET HINGE (LH) <i>HH</i>	1	\$87.70	\$87.70
BONNET LOCK <i>st</i>	1	\$132.60	\$132.60
CATCH, HOOD AUXILIARY HOOK <i>HH</i>	1	\$8.60	\$8.60
RADIATOR GRILLE <i>broken</i>	1	\$438.00	\$438.00
RADIATOR GRILLE EMBLEM <i>HH</i>	1	\$88.00	\$88.00
FRONT BUMPER COVER <i>HH</i>	1	\$499.90	\$499.90
FRONT BUMPER REINFORCEMENT <i>st</i>	1	\$696.40	\$696.40
FRONT BUMPER REINFORCEMENT ABSORBER <i>HH</i>	1	\$115.70	\$115.70
FRONT BUMPER LOWER REINFORCEMENT <i>st</i>	1	\$364.20	\$364.20
FRONT BUMPER LOWER REINFORCEMENT BRACKET <i>HH</i>	1	\$330.00	\$330.00
FRONT SIDE MEMBER REINFORCEMENT PANEL (LH/RH) <i>HH</i>	2	\$ 320.70	\$641.40
FRONT SIDE MEMBER SIDE COVER <i>HH</i>	1	\$ 172.50	\$172.50
FRONT BUMPER SPONGE <i>HH</i>	1	\$78.80	\$78.80
FRONT BUMPER LOWER GRILLE <i>defunct mounting</i>	1	\$148.60	\$148.60
LAMP ASSY, FOG, RH <i>HH</i>	1	\$920.00	\$920.00
LAMP ASSY, FOG, LH <i>mainly crack</i>	1	\$920.00	\$920.00
FRONT BUMPER CLIPS <i>HH</i>	1	\$22.00	\$22.00
FRONT BUMPER SIDE RETAINER <i>HH</i>	1	\$77.00	\$77.00
FRONT LOWER PANEL <i>st</i>	1	\$320.65	\$320.65
FRONT LOWER SIDE RAIL (LH/RH) <i>HH</i>	2	\$230.80	\$461.60
FRONT LOWER CROSSMEMBER <i>HH</i>	1	\$357.70	\$357.70
FRONT UNDER COVER <i>HH</i>	1	\$180.80	\$180.80
ENGINE UNDER COVER (RR) <i>HH</i>	1	\$457.40	\$457.40
ENGINE UNDER COVER CENTER <i>HH</i>	1	\$523.40	\$523.40
FRONT BUMPER TOP GARNISH <i>HH</i>	1	\$225.40	\$225.40
COVER, FRONT BUMPER HOLE, RH <i>st</i>	1	\$28.38	\$28.38
COVER, FRONT BUMPER HOLE, LH <i>st</i>	1	\$28.38	\$28.38
ABSORBER, FRONT BUMPER, LOWER <i>mainly broken</i>	1	\$127.70	\$127.70
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>	1	\$3,455.00	\$3,455.00
HEADLAMP ECU <i>mainly broken</i>	1	\$682.60	\$682.60
HEAD LAMP PANEL (LH) <i>st</i>	1	\$240.10	\$240.10
TOP PANEL CENTRE <i>st</i>	1	\$364.98	\$364.98
TOP PANEL SIDE <i>st</i>	1	\$145.90	\$145.90
BRACE PANEL <i>HH</i>	1	\$75.20	\$75.20
RADIATOR ASSY <i>st</i>	1	\$1,841.80	\$1,841.80
RADIATOR FAN GRILLE <i>HH</i>	1	\$632.40	\$632.40

BIFROST AUTO PTE LTD

REPAIR SUPPLEMENTARY

DATE: 2-Nov-20

MODEL: TOYOTA PRIUS

INSURANCE: China Taiping

VEHICLE NO.: SHA 4847 Y (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
UNIT ASSY, HEADLAMP, RH (LED) <i>mainly broken</i>	1	\$3,455.00	\$3,455.00
HEAD LAMP PANEL (RH) <i>1st</i>	1	\$240.10	\$240.10
TOP PANEL SIDE <i>1st</i>	1	\$145.90	\$145.90
BATTERY <i>detected damaged 50% SH</i> SN	1	\$220.00	\$220.00
SUB TOTAL			
LESS 20% <i>25%</i>			\$4,061.00
DISCOUNTED TOTAL			\$812.20
			\$3,248.80
SUB TOTAL			
			\$0.00

2637.60
✓
✓
✓
110/- SH

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1 year

2kk Auto

8

3023.60

25% 2267.70

110.00 SH

2377.70