

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A162001169314953

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBM 3523X

at Workshop m/s R.P.

of \_\_\_\_\_

Insured: EK 448A

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|                                     |                                     |
|-------------------------------------|-------------------------------------|
| <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| N/S                                 | O/S                                 |
| <input type="checkbox"/>            | <input type="checkbox"/>            |

Bal. or Market Value: 411K.

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 6 days

Res.: Yes or No

Ltm Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

318F  
Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: Dep 1600

Veh No: FBM 3523X

Yr Regn: 10/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki

Burgmen c.c. 200

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 5thly Rep

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MLCC91327H0403925

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or ok

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/90-13

R: 130/70-12

BS / DUN / EXNOVA / GY / FS / EIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6

Rear

R/Bal. \_\_\_\_\_ mm

R/Bal. 6 mm

L/Bal. \_\_\_\_\_ mm

L/Bal. \_\_\_\_\_ mm

D.O.A. 25/10/20

D.O.I. 27/10/20

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

0/K, n/s body  
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 93812 net 7188  
62 m/s have 9.1A

25/11/20 d/s #7100 confirmed with Alan.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee:

☐

Site Insp (\$ \_\_\_\_\_)

☐

Interview (\$ \_\_\_\_\_)

☐

Tech. Invs (\$ \_\_\_\_\_)

☐

Weekend (\$ \_\_\_\_\_)

S + RS, \$ \_\_\_\_\_

Photos

Others

TOTAL

FASTECH AUTO PTE LTD  
1 KAKI BUKIT AVE 6 #01-48  
SINGAPORE 417883

WMA Cecilia

Not Authorized  
27/10/20  
2/5 @ 7100 / 6 days

VEHICLE No: FBM 3523X

|      |                                         |         |               |             |     |
|------|-----------------------------------------|---------|---------------|-------------|-----|
| 1PC  | FRONT FORK ASSY                         | beat/wr | 680           | \$1,150.00  | /   |
| 1PC  | WINDSHIELD                              | cne     | 750           | \$968.00    | /   |
| 1PC  | HEADLAMP                                | cne     | 520           | \$655.00    | /   |
| 1PC  | LAMP STAY                               | su      |               | \$225.00    | X   |
| 1PC  | FRONT FENDER                            | cne     | 145           | \$165.00    | /   |
| 1SET | FRONT FAIRING COVER                     | 520     | 1250          | \$1,500.00  | /   |
| 2PCS | SIDE MIRRORS @ \$155.00                 | ms sc   |               | \$310.00    | 1PC |
| 1PC  | HANDLE BAR                              | su      |               | \$135.00    | X   |
| 2PCS | HANDLE BAR BALANCERS @ \$50.00          | 11      |               | \$100.00    | X   |
| 1PC  | HANDLE BAR GRIP                         | 11      |               | \$55.00     | X   |
| 1PC  | BRAKE LEVER LH                          | su      |               | \$150.00    | X   |
| 1PC  | BRAKE LEVER RH                          | scr     | 115           | \$150.00    | /   |
| 2PCS | FRONT SIGNAL LAMPS @ \$165.00           | 2/5 cm  | 105           | \$330.00    | 1PC |
| 2PCS | LOWER BELLY PANELS @ \$450.00           | 7.5     | 380 x 2 = 700 | \$900.00    | /   |
| 2PCS | LOWER COWLING CENTRE GRILLES @ \$180.00 | 7.5     |               | \$360.00    | /   |
| 2PCS | FOOT STEP GARNISHS @ \$185.00           | 7.5     |               | \$370.00    | /   |
| 2PCS | FOOT STEPS @ \$85.00                    | 7.5     |               | \$170.00    | /   |
| 1PC  | REAR EXHAUST                            | no/beat | 1450          | \$1,650.00  | /   |
| 1PC  | REAR EXHAUST FRONT COVER                | 7.5     |               | \$65.00     | /   |
| 1PC  | REAR EXHAUST CENTRE COVER               | cu7     |               | \$99.00     | /   |
| 1PC  | REAR EXHAUST REAR COVER                 | cu7     |               | \$60.00     | /   |
| 1PC  | TAILLAMP                                | 11      |               | \$355.00    | X   |
| 1PC  | METER                                   | 11      |               | \$850.00    | X   |
| 1PC  | METER COVER                             | cne     | 300           | \$388.00    | /   |
| 1PC  | FRONT INNER CENTRE COVER                | cne     | 485           | \$620.00    | /   |
| 1PC  | FRONT INNER CENTRE OUTER COVER          | cne     | 290           | \$350.00    | /   |
| 1PC  | MAIN STAND                              | 11      |               | \$158.00    | X   |
| 1PC  | SIDE STAND                              | 11      |               | \$125.00    | X   |
| 1PC  | ENGINE COVER                            | scr     | 245           | \$350.00    | /   |
|      |                                         |         |               | \$12,763.00 |     |

(102)

1-8314  
102  
748260

S.NETT

|      |                                            |         |          |     |
|------|--------------------------------------------|---------|----------|-----|
| 1PC  | FRONT WINDSHIELD FRT LICENCE PLATE STICKER | ner     | \$20.00  | 10  |
| 1SET | FRONT WINDSHIELD STICKER                   | 11      | \$100.00 | X   |
| 1SET | FRONT FENDER ABS STICKER                   | 11      | \$60.00  | 30  |
| 1SET | FRONT LED LAMP                             | daye    | \$500.00 | 250 |
| 1PC  | REAR BOX                                   | no/beat | \$980.00 | 680 |
| 1PC  | REAR BOX BRACKET                           | 11      | \$180.00 | X   |

TO CHECK WIRING  
TO STRAIGHTEN FRONT BODY ALIGNMENT

11 \$30.00 X  
\$450.00 300

TO SPRAY PAINTING

LABOUR FOR PANEL BEATING & REPLACED PARTS

\$600.00 280

\$500.00 300

TOTAL

\$16,183.00

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9332-6  
202  
7466