

**SIN WEE CHUAN SPRAY PAINTING & SERVICE**

BLK 3021-A, UBI ROAD 1, # 01-40, SINGAPORE 408715

TEL : 67480573 FAX : 67435192

GST M90357486J

Invoice No : 9177/18

20-08-2019

Accident Involving SLE 8421 Y And SJV 7574 E on 07-08- 2017

Re : Repair Bill For Veh No SJV 7574 E

Item	Description	Qty	U/Price	SSAmount		
1.	Rear Bumper (AMG C63) ✓ DE	01		2,200.00	1500	1800
2.	Rear Bumper Carrier Bracket × NN	01		230.00	×	
3.	Rear Bumper Carrier ✓ BT	01		520.20	✓	
4.	Rear Bumper Lower Defuser × NN	01		455.00	×	
5.	Front Driver Seat Head Rest ✓ ACT	01		655.00		250(local repair)
6.	Front Passenger Seat Head Rest × NN	01		655.00	×	
Parts Total				4,715.20	2020.2	2320.2
					-10%: 1818.18	2088.18
Labour Charge						
Labour To Re-Spray Rear Bumper.				300.00		200
To Panel Beating /Remove & Install New Parts				300.00		200
Labour Charge				600.00		

Parts Total	SS 4,715.20
Labour Charge	SS 600.00
Parts & Labour	SS 5,315.20
GST 7%	SS 372.06
Grand Total	SS 5,687.26

2468.18 2738.18

-20%: ~~1950~~ 2200

3 days

SIN WEE CHUAN SPRAY PAINTING & SERVICE

MIKE LAW
HP 91074888

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: