



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

TP 1st Cap
Asher

WVWZZZAUZIEW382448

Page No. 1

Vehicle No. SKN91833 VOLKSWAGEN GOLF

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR ADJUSTMENT	
PARTS (LIST ITEMS)						
1	REAR BOOTLID <i>Dented</i>		1905.10		<i>1450</i>	
1	REAR BOOTLID LOCK <i>the an</i>		197.20	<i>+</i>		
1	REAR BOOTLID WEATHERSTRIP <i>at</i>		323.80		<i>268</i>	
2	REAR BOOTLID RUBBER STOPPER LH & RH @\$30.00 <i>xcen</i>		60.00	<i>+</i>		
1	REAR BOOTLID INNER TRIM COVER <i>xcen</i>		221.00	<i>+</i>		
1	REAR BOOTLID " BLUEMOTION TECHNOLOGY " EMBLEM <i>xcen</i>		81.00	<i>✓</i>		
1	REAR BOOTLID " TSI " EMBLEM <i>xcen</i>		76.00	<i>✓</i>		
1	REAR BOOTLID CENTRE LOGO BADGE <i>xcen</i>		126.50	<i>+</i>		
1	REAR BUMPER <i>Deformed</i>		1085.00	<i>✓</i>		
1	REAR BUMPER REINFORCEMENT <i>Bent</i>		523.20	<i>✓</i>		
1	REAR BUMPER TOW COVER <i>Deformed</i>		101.00	<i>✓</i>		
2	REAR BUMPER REFLECTOR LH & RH @\$127.60 <i>2Hut</i>		255.20		<i>122.60</i>	
1	REAR BUMPER FOAM UPPER BEAM GARNISH <i>xcen</i>		211.00	<i>✓</i>		
2	REAR BUMPER SIDE RETAINER LH & RH @\$131.00 <i>xcen</i>		262.00	<i>+</i>		
2	REAR BUMPER SIDE HOLDERS LH & RH @\$107.30 <i>xcen</i>		214.60	<i>+</i>		
1	REAR BUMPER LOWER GARNISH <i>at</i>		535.50		<i>323</i>	
1	REAR BOOTLID LAMP RH <i>xcen</i>		410.00	<i>+</i>		
1	REAR TAILLAMP RH <i>xcen</i>		735.00	<i>+</i>		
1	REAR TAILLAMP LOWER BRACKET RH <i>xcen</i>		141.00	<i>+</i>		
1	REAR END PANEL <i>Dented</i>		990.00	<i>+</i>	<i>688</i>	
1	REAR END PANEL INNER TRIM <i>on lid</i>		137.50	<i>✓</i>		
			8591.60			
less			10%	859.16	10%	
				7732.44		
SPECIAL NETT ITEMS						
1 SET	REAR BUMPER CLIPS <i>xcen</i>		100.00	<i>+</i>	<i>30</i>	
1 SET	REAR CAR PLATE WITH COVER <i>xcen</i>		70.00	<i>+</i>	<i>50</i>	
1 SET	REAR END PANEL LOWER TOP GARNISH CLIPS <i>xcen</i>		80.00	<i>+</i>	<i>20</i>	
1	REAR END PANEL LOWER SEALANT <i>xcen</i>		100.00	<i>+</i>		
1 SET	REAR BUMPER LOWER GARNISH CLIPS <i>xcen</i>		80.00	<i>+</i>	<i>30</i>	
1 SET	REVERSE SENSOR <i>Dented</i>		450.00	<i>+</i>	<i>200</i>	
Total Parts			8612.44			



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Page No. 2

Vehicle No. SLN9183S VOLKSWAGEN GOLF

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	700
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	800
3	To remove , fefix wiring system at accident damage areas and check for proper function	150.00	30
4	To transfer rear boot mechanism	120.00	60
5	To perform anti-rust treatment on affected areas	270.00	60
6	To conduct water seepage test	120.00	+ 1450
	Labour Total :	3460.00	
	TOTAL (PARTS & LABOUR):	12072.44	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
n/s 28/10/20.

05 Days -

total: 6344.17

h/s: SK

SK