

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMG5298J
Chassis No : JHMRU1830JX200889
Model : HRV LX-SIN CVT YM 2018
Owner's Name : ANG TIAN SUEH
Ins Policy No :
Date of Accident : 26/10/2020

Document No. : SQT20003475
Date : 26. Oct 2020
Customer No. : WZF002
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B5670890
Date | Time : 26. Oct 2020 11:30:47 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ANG TIAN SUEH OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE LT ACC DATE: 26/10/2020 SURVEYED BY: DATE: REF NO: TP INSURER: MSFIRST CAPITAL TP VEH: SHA9506Z						
68100-T7A-J20ZZ	TAIL GATE COMP <i>bt</i>	1	877.90 <i>855.70</i>	25	658.42 <i>641.74</i>	6.09	704.51
74440-T7A-003	WEATHERSTRIPTAILGATE <i>? x sue</i>	1	101.30	25	75.97	5.32	81.29
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY <i>? x sue</i>	1	167.40	25	125.55	8.79	134.34
75722-T7W-A01	EMBLEMRR. <i>re</i>	1	14.60	25	10.95	0.77	11.72
75725-T8N-T00	EMBLEM, RR. I-VTEC <i>re</i>	1	15.90	25	11.92	0.83	12.75
04715-T7A-900ZZ	FACE, RR. BUMPER <i>de</i>	1	463.70	25	347.77	24.34	372.11
04717-T7A-J00ZZ	FACE, R. RR. BUMPER CORNER <i>? x sue</i>	1	96.50	25	72.37	5.07	77.44
04718-T7A-J00ZZ	FACE, L. RR. BUMPER CORNER <i>? x sue</i>	1	96.50	25	72.37	5.07	77.44
33505-T7A-J01	REFLECTOR ASSY, RR. <i>2 x sue</i>	1	170.80	25	128.10	8.97	137.07
33555-T7A-J01	REFLECTOR ASSY, L. RR. <i>? x sue</i>	1	170.80	25	128.10	8.97	137.07
71593-T7A-J00	SPACER, R. RR. BUMPER SIDE <i>re</i>	1	17.30	25	12.97	0.91	13.88
71598-T7A-J00	SPACER, L. RR. BPR S <i>re</i>	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP, BUMPER <i>re</i>	8	2.30	25	13.80	0.97	14.77
66100-T7A-300ZZ	PANEL COMPRR. <i>? x sue</i>	1	382.70	25	287.02	20.09	307.11
84640-T7A-J01ZA	LINING ASSY, RR. PANEL <i>? x sue</i>	1	45.00	25	33.75	2.36	36.11
34150-T7A-J31	LIGHT ASSY, R. LID <i>x sue</i>	1	276.90	25	207.67	14.54	222.21
34155-T7A-J31	LIGHT ASSY, L. LID <i>x sue</i>	1	276.90	25	207.67	14.54	222.21
33502-T7A-J31	LAMP UNIT, R. <i>x sue</i>	1	412.00	25	309.00	21.63	330.63
33552-T7A-J31	LAMP UNIT, L. <i>x sue</i>	1	412.00	25	309.00	21.63	330.63

Printed on 26/10/2020 11:49:18 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)

Body and Body Repair

+65 6841 3838

Website: www.honda.com.sg

or 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMG5298J
Chassis No : JHMRU1830JX200889
Model : HRV LX-SIN CVT YM 2018
Owner's Name : ANG TIAN SUEH
Ins Policy No :
Date of Accident : 26/10/2020

Document No. : SQT20003475 Page 2
Date : 26. Oct 2020
Customer No. : WZF002
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B5670890
Date | Time : 26. Oct 2020 11:30:47 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>ne /</i>	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 <i>ne /</i>	1	8.70	25	6.52	0.46	6.98
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>ne /</i>	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT <i>ne /</i>	1	5.00	25	3.75	0.26	4.01
91501-S70-003	FASTENER BW/SHIELD <i>ne /</i>	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B <i>ne /</i>	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD <i>ne /</i>	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>ne /</i>	2	60.00		120.00	8.40	128.40
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ? <i>Xsu</i>	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>Xsu</i>	1	45.00		45.00	3.15	48.15
Sum Item					3579.13	250.56	3,829.69
BOSUN	SUNDRIES	1	100.00 <i>50 /</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	120.00 <i>/ /</i>		120.00	8.40	128.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00 <i>250 /</i>		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00 <i>250 /</i>		280.00	19.60	299.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00 <i>480 /</i>		560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00 <i>480 /</i>		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00 <i>325 /</i>		650.00	45.50	695.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00 <i>/ /</i>		650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00 <i>325 /</i>		650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN <i>0650</i>	1	5200.00 <i>1300(2600) Xsu</i>		5200.00	364.00	5564.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>0520</i>	1	3640.00 <i>1566(2600) Xsu</i>		3640.00	254.80	3894.80
BOBC	BODY UNDERSIDE COATING (N)	1	350.00 <i>250 /</i>		350.00	24.50	374.50
Sum Labor					13040.00	912.80	13,952.80

Survey By

Refuse - Up 9000068

Printed on 26/10/2020 11:49:18 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Document No. : SQT20003475
Date : 26. Oct 2020
Customer No. : WZF002
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B5670890
Date | Time : 26. Oct 2020 11:30:47 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
			Total Amount	16,619.13	1,163.36
			Total (Inclusive of GST)		17,782.49

Date of Accident : 26/10/2020
 Date & Time : 28/10/2020 @ 10:15
 Description : 6 days / 9 days with end panel
 Signature : [Signature]
 Reason before panel : Reason before panel

Date:



KAH MOTOR CO. SDN. BHD.

Supplementary

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	CU0032744 / MS FIRST CAPITAL	Document No:	SVO20057042
Chassis No:	JHMRU1830JX200889	Printed By:	IVANTEO
License No:	SMG5298J	Order Date:	28. October 2020
Mileage:	158024	Order Time:	10:35:30 AM
Engine No:	L15B5670890	Service Advisor:	IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ANG TIAN SUEH OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE LT ACC DATE: 26/10/2020 SURVEYED BY: DATE: REF NO: TP INSURER: MSFIRST CAPITAL TP VEH: SHA9506Z SUPPLEMENTARY PART						
90661-SC7-003	GROMMET SCREW nec ✓	2.	2.40	25.	3.60	0.25	3.85

GST Amount is calculated from individual line(s)