

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED	Document No.	: SQT20003475	Page	1
	36 ROBINSON ROAD	Date	: 26. Oct 2020		
	#16-01 CITY HOUSE	Customer No.	: WZF002		
	SINGAPORE 068877	Svc Advisor	: IVAN TEO BOON KIAT		
Registration No	: SMG5298J	Engine No	: L15B5670890		
Chassis No	: JHMRU1830JX200889	Date Time	: 26. Oct 2020 11:30:47 AM		
Model	: HRV LX-SIN CVT YM 2018	Surveyor Name	:		
Owner's Name	: ANG TIAN SUEH	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 26/10/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: ANG TIAN SUEH						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE LT						
	ACC DATE: 26/10/2020						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: MSFIRST CAPITAL						
	TP VEH: SHA9506Z						
68100-T7A-J20ZZ	TAIL GATE COMP <i>bt</i>	1	877.90	25	658.42	46.09	704.51
74440-T7A-003	WEATHERSTRIPTAILGATE ?	1	101.30	25	75.97	5.32	81.29
74800-T7Y-K01	LOCK ASSY, TAILGATE ASSY ?	1	167.40	25	125.55	8.79	134.34
75722-T7W-A01	EMBLEMRR. <i>re</i>	1	14.60	25	10.95	0.77	11.72
75725-T8N-T00	EMBLEM, RR. I-VTEC <i>re</i>	1	15.90	25	11.92	0.83	12.75
04715-T7A-900ZZ	FACE, RR. BUMPER <i>de</i>	1	463.70	25	347.77	24.34	372.11
04717-T7A-J00ZZ	FACE, R. RR. BUMPER CORNER ?	1	96.50	25	72.37	5.07	77.44
04718-T7A-J00ZZ	FACE, L. RR. BUMPER CORNER ?	1	96.50	25	72.37	5.07	77.44
33505-T7A-J01	REFLECTOR ASSYR. RR. <i>3X</i>	1	170.80	25	128.10	8.97	137.07
33555-T7A-J01	REFLECTOR ASSYL. RR. ?	1	170.80	25	128.10	8.97	137.07
71593-T7A-J00	SPACER, R. RR. BUMPER SIDE <i>re</i>	1	17.30	25	12.97	0.91	13.88
71598-T7A-J00	SPACER, L. RR. BPR S <i>re</i>	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP, BUMPER <i>re</i>	8	2.30	25	13.80	0.97	14.77
66100-T7A-300ZZ	PANEL COMPRR. ?	1	382.70	25	287.02	20.09	307.11
84640-T7A-J01ZA	LINING ASSYRR. PANEL ?	1	45.00	25	33.75	2.36	36.11
34150-T7A-J31	LIGHT ASSY, R. LID X	1	276.90	25	207.67	14.54	222.21
34155-T7A-J31	LIGHT ASSY, L. LID X	1	276.90	25	207.67	14.54	222.21
33502-T7A-J31	LAMP UNIT, R. X	1	412.00	25	309.00	21.63	330.63
33552-T7A-J31	LAMP UNIT, L. X	1	412.00	25	309.00	21.63	330.63

Printed on 26/10/2020 11:49:18 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMG5298J
Chassis No : JHMRU1830JX200889
Model : HRV LX-SIN CVT YM 2018
Owner's Name : ANG TIAN SUEH
Ins Policy No. :
Date of Accident : 26/10/2020

Document No. : SQT20003475 **Page** 2
Date : 26. Oct 2020
Customer No. : WZF002
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B5670890
Date | Time : 26. Oct 2020 11:30:47 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER <i>ne /</i>	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 <i>ne /</i>	1	8.70	25	6.52	0.46	6.98
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER <i>ne /</i>	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT <i>ne /</i>	1	5.00	25	3.75	0.26	4.01
91501-S70-003	FASTENER BW/SHIELD <i>ne /</i>	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B <i>ne /</i>	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD <i>ne /</i>	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>ne /</i>	2	60.00		120.00	8.40	128.40
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ?	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>X</i>	1	45.00		45.00	3.15	48.15
Sum Item					3579.13	250.56	3,829.69

BOSUN	SUNDRIES	1	100.00 50		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	120.00		120.00	8.40	128.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00 250		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	280.00 250		280.00	19.60	299.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00 480		560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00 480		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00 325		650.00	45.50	695.50
BG02R	REPLACE RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00 325		650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	5200.00 1300(2600)?		5200.00	364.00	5564.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>es 20</i>	1	3640.00 1560(2600)? 2600?		3640.00	254.80	3894.80
BOBC	BODY UNDERSIDE COATING (N)	1	350.00 250		350.00	24.50	374.50
Sum Labor					13040.00	912.80	13,952.80

Survey By

Refine - up 920068

Printed on 26/10/2020 11:49:18 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

KAH MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMG5298J
Chassis No : JHMRU1830JX200889
Model : HRV LX-SIN CVT YM 2018
Owner's Name : ANG TIAN SUEH
Ins Policy No. :
Date of Accident : 26/10/2020

Document No. : SQT20003475 **Page** 3
Date : 26. Oct 2020
Customer No. : WZF002
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L15B5670890
Date | Time : 26. Oct 2020 11:30:47 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Date & Time	28/10/2020 @ 10:15						
Excess	6 days / 9 days ? with end panel						
Status							
Signature							
					Total Amount	16,619.13	1,163.36
					Total (Inclusive of GST)		17,782.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 26/10/2020 11:49:18 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.