

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and acknowledged by Repairer

Special Approval from Insurance Company

Not Authorised
Resurvey B4 paint

AAD2010-102

81144.53

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 001019626G

SHB7648E

Vehicle No.:
Chassis No.:
Vehicle Make: 26 OCT 2020
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHB7648E

JTDKB3FUX03082560

TOYOTA

PRIUS

23/10/2020

FIRST CAPITAL

1/8/2019

- | | PART |
|---|--|
| 1 | COVER, REAR BUMPER |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER |
| 1 | GUARD, REAR BUMPER, CENTER |
| 1 | RETAINER, REAR BUMPER SIDE, RH |
| 1 | PANEL SUB-ASSY, BACK DOOR |
| 1 | PANEL SUB-ASSY, BODY LOWER BACK |
| 1 | FILLER, REAR BUMPER EXTENSION, RH |
| 1 | FILLER, REAR BUMPER EXTENSION, LH |
| 1 | LENS AND BODY, REAR LAMP, LH |
| 1 | LENS & BODY, REAR COMBINATION LAMP, LH |
| 1 | LENS AND BODY, REAR LAMP, RH |
| 1 | LENS & BODY, REAR COMBINATION LAMP, RH |
| 1 | ORNAMENT SUB-ASSY, BACK DOOR |
| 1 | PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2 |
| 1 | PLATE, BACK DOOR NAME, NO.1 |

LIST			
\$	R	442.60	X
\$	Ry	332.70	✓
\$	nd	576.30	✓
\$	Sn	117.70	X
\$	R	1,147.80	X
\$	Sn	650.30	X
\$	Sn	123.70	X
\$	mgmt Sn	123.70	✓
\$	Sn	502.00	} X
\$	Sn	443.30	
\$	Sn	502.00	
\$	Sn	451.80	
\$	Sn	47.90	
\$	Sn	54.60	
\$	Sn	54.60	
TOTAL	\$	5,571.00	
25%	\$	1,392.75	
	\$	4,178.25	

Special Nett

1SET PARKING AID	\$	Sn	700.00	X
1SET REAR BUMPER CLIP	\$	nn	85.00	X
1 REAR BUMPER PROTECTOR	\$	nn	180.00	X
1 REAR BUMPER RETAINER CLIP	\$	nn	75.00	X
1SET TAILLAMP CLIP	\$	nn	50.00	X

Trans-cab Auto Services Pte Ltd**AAD2010-102**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7648E

1 BOOTLID STICKER 'TRANSCAB'	\$	nn	100.00	X
1 BOOTLID STICKER '65553333'	\$	nn	100.00	X
1SET REAR NUMBER PLATE WITH HOLDER	\$	nn	120.00	X
TOTAL	\$		1,410.00	

TOTAL PARTS	\$		5,588.25
--------------------	-----------	--	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	nn	240.00	X
----	----	--------	---

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	nn	380.00	X
----	----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$		1,600.00	150/
----	--	----------	------

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$		380.00	X
----	--	--------	---

Putty And Spray Painting Of The Affected Portion.

\$		1,600.00	220/
----	--	----------	------

To reinstall rear bumper parking sensor.

\$		170.00	X
----	--	--------	---

To Check Electrical Lighting Concerned.

\$	nn	170.00	X
----	----	--------	---

To check steering geometry and computer wheel alignment

\$	nn	220.00	X
----	----	--------	---

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$	nn	170.00	X
----	----	--------	---

TOTAL	\$		4,930.00
--------------	-----------	--	-----------------

Over All Total	\$		10,518.25
-----------------------	-----------	--	------------------