

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20011706/R1GS3Q2

**Date:** 17/02/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SHA8843G	<b>Insured Vehicle No :</b>	SHA6541R
Date of Loss: 26/10/2020	Nature of Claim: TP	Claim No: MCT20100445

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHA8843G</b>	
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No: 2ZRR969408
Reg. Date:	09/12/2016 (Man. Year: 2016)	Chassis No: JTDKB3FU403538763
Colour:	Yellow	Odometer: 541652 km
Engine Capacity:	1798 cc	
Market Value/New Car Price:	N/A	
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Triangle 5 mm	Rear Left Side:	Triangle 5 mm
Front Right Side:	Triangle 5 mm	Rear Right Side:	Triangle 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,962.47	138.70	1,823.77	92.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	780.00	1,200.00	60.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>3,942.47</b>	<b>918.70</b>	<b>3,023.77</b>	<b>76.70</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	275.97	64.31	211.66	76.70
<b>Nett Amount (\$\$)</b>	<b>4,218.44</b>	<b>983.01</b>	<b>3,235.43</b>	<b>76.70</b>
<b>+ Loss of Use (3.0 x S\$40.00/day) (\$\$)</b>		120.00		
<b>+ Car Rental (3.0 x S\$117.20/day) (\$\$)</b>		351.60		
		<b>(S\$)</b>		
		1,454.61		
<b>Liabile Amount (50.00%) (\$\$)</b>		<b>727.31</b>		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>734.76</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>650.00</b>		

### INSPECTION

Date of Assignment:	27/10/2020	
Date Inspected:	28/10/2020	Inspected At: 31 CORPORATION RD
		Repairer: Ding Auto Pte Ltd (HQ)
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jan 2021)
<b>Parts:</b>	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHA8843G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Repair	933.10 FL	*- FL
2	1		*FRONT FENDER EMBLEM -HYBRID RH	Necessary	51.60 FL	*51.60 FL
3	1		*FRONT BUMPER RETAINER RH	Serviceable	92.30 FL	*- FL
4	1		*FRONT DOOR RH	Repair	1,226.30 FL	*- FL
5	1		*REPAIR FRONT BUMPER (NPA)	Not Necessary	0.00 FS	*- FS
6	1		*FRONT DOOR STICKER -COMFORT DELGRO RH	Necessary	150.00 FS	*100.00 FS
7	1		*FRONT DOOR TRIM BOARD CLIP SET RH	Not Necessary	35.00 FS	*- FS
8	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,538.30</b>	<b>151.60</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	575.83	12.90
<b>Total Parts (S\$)</b>	<b>1,962.47</b>	<b>138.70</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREA	New	700.00	350.00
2	RUST PROOFING	New	80.00	30.00
3	R&R FRONT DOOR COMPONENTS RH	New	150.00	0.00
4	DIAGNOSTIC (CLEAR FAULT CODE) & RESETTING POWER WINDOW (AUTO)	New	180.00	0.00
5	CHECK WIRING & LIGHTING SYSTEM	New	120.00	0.00
6	RESPRAY FRONT BUMPER	New	250.00	0.00
7	RESPRAY FRONT FENDER RH	New	250.00	200.00
8	RESPRAY FRONT DOOR RH	New	250.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,980.00</b>	<b>780.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >