

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B**AAD2010-101***Not Authorised**1/1 Sep \$1,200.00*

Vehicle No.:

Chassis No.:

Vehicle Make:

26 OCT 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC5678B

VF1ABL15AUC279839

RENAULT

LATITUDE

22/10/2020

III

4/11/2014

	PART		LIST	
		\$	CM 561.70	✓
		\$	NC 411.90	✓
1	1 BUMPER COVER REAR	\$	SL 98.10	} X
2	1 BUMPER LOWER REAR	\$	SL 82.10	
3	1 BUMPER BRACKET CTR REAR	\$	SL 59.80	
4	1 BUMPER BRACKET SIDE RH REAR	\$	SL 80.80	
5	1 BUMPER RETAINER RH REAR	\$	SL 54.20	
7	1 BUMPER BRACKET SIDE LH REAR	\$	SL 547.80	
8	1 BUMPER RETAINER LH REAR	\$	NC 114.50	
10	1 BUMPER BEAM REAR	\$	NC 114.50	
11	1 BUMPER BEAM BRACKET LH REAR	\$	NC 745.80	
12	1 BUMPER BEAM BRACKET RH REAR	\$	SL 404.56	
13	1 OUTER PANEL REAR (End Panel)	\$	NC 1,677.20	
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	SL 16.60	
15	1 BOOT REAR	\$		
16	1 BUMPER REFLECTOR LH	\$		
		\$	4,969.56	
		10% \$	496.96	
		\$	4,472.60	

Specical Nett

1	1SET PARKING AID	\$	SL 700.00	X
2	1SET REAR BUMPER CLIP	\$	NC 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	NC 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	NC 10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	NC 20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	NC 10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	NC 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	NC 22.00	X

Trans-cab Auto Services Pte Ltd

AAD2010-101

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B

- 9 1SET BUMPER LOWER REAR CLIP
10 1 EXHAUST MOUNTING REAR
14 1 REAR BOOT STICKER 'Trans-cab'
15 1 REAR BOOT STICKER '6555-3333'

	\$	<i>nn</i>	66.00	✓
	\$	<i>nn</i>	17.82	X
	\$	<i>nn</i>	80.00	X
	\$	<i>nn</i>	80.00	X
TOTAL	\$		1,124.82	
TOTAL PARTS	\$		5,597.42	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	<i>220/</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	<i>200/</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	<i>60/</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	X
To repair and realign rear exhaust pipe.	\$	<i>nn</i>	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i>	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i>	170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5678B

AAD2010-101

To Check Electrical Lighting Concerned.

\$

~ 170.00 X

TOTAL \$

7,580.00

Over All Total \$

13,177.42

(LUMP SUM)

Repair Days

~~10~~ DAYS

2 day

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: