



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE

DATE : 3/11/2020
ACC DATE : 21/10/2020
POLICY NO : 5117140669
SHEET NO. 1 OF 1 SHEET

Attention: Motor Claim Department

RE : VEHICLE NO : XE4783L Scania P410 (Infiniti Marine Pte Ltd)

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	1	Front windscreen <i>CR</i>	1480	1,800.00
2	1	Front corner panel RH <i>XSL</i>		826.00X
3	1	Bonnet frame structure <i>bt</i>	2410	3,917.00
4	1	Bonnet badge <i>CR</i>	137	270.00
5	1	Bonnet emblem (scania) <i>new</i>	288	378.00
6	1	Bonnet emblem(P410) <i>new</i>	135	317.00
7	1	Bonnet emblem(XT) <i>new</i>		178.00
8	1	Bonnet center pad <i>bt</i>		1,735.00
9	1	Bonnet bottom pad <i>bt</i>		1,237.00
10	1	Bonnet bottom grille <i>CR</i>		375.00
11	1	Bonnet center grille <i>CR</i>		410.00
12	1	Bonnet side grille <i>RH-LH-XSL</i>	978.00	1,956.00X
13	1	Bonnet center lock <i>bt</i>		479.00
14	1	Bonnet side lock <i>RH-LH-XSL</i>	(1pc) 395.00	790.00X
15	2	Bonnet side lock catch <i>XSL</i>	40.00	80.00X
16	2	Bonnet side lock bracket <i>XSL</i>	100.00	200.00X
17	2	Bonnet absorber <i>XSL</i>	417.00	834.00X
18	1	Bonnet top handle rail <i>CR</i>		1,217.00
19	2	Bonnet hinge <i>XSL</i>	318.00	636.00X
20	1	Wiper garnish center <i>CR</i>		410.00
21	1	Wiper side garnish <i>RH-LH-XSL</i>	(1pc) 210.00	420.00
22	2	Wiper garnish bracket center <i>XSL</i>	90.00	180.00X
23	2	Wiper garnish bracket side <i>XSL</i>	100.00	200.00X
24	1	Wiper panel <i>repair</i>		2,100.00XR
25	1	Wiper link <i>bt</i>	1572	4,170.00
26	1	Front panel <i>repair</i>		2,178.00XR
27	1	Air cleaner box outer <i>CR</i>		890.00
28	1	Air cleaner box inner <i>CR</i>		3,987.00
29	1	Cabin front absorber <i>RH-LH-XSL</i> <i>N/S</i> <i>photo?</i> (No photo)	1pc (450) 710.00	1,420.00X
30	2	Cabin absorber bracket <i>XSL</i>	890.00	1,780.00X
31	2	Cabin absorber bottom bracket <i>XSL</i>	670.00	1,340.00X
32	1	Cabin roller bar <i>XSL</i>		3,850.00X
33	1	Air con dryer <i>bt</i>	360	670.00
34	1	Air con suction pipe <i>bt</i>		1,970.00X
35	1	Air con discharged pipe <i>bt</i>		875.00X
36	1	Air con discharged pipe 2 <i>bt</i>		715.00X

17690

- 7 1 Air con cooling pipe ~~bt~~
 38 1 Air con liquid pipe ~~bt~~
 39 1 Air con small pipe ~~bt~~
 40 1 Air con condenser ~~bt~~
 41 1 Turbo intercooler ~~bt~~
 42 1 Intercooler mesh X ~~SUL~~
 43 1 Front bumper repair
 44 1 Brake booster X ~~SUL~~
 45 1 Radiator top cover X ~~SUL~~
 46 1 Dash board top ~~cut~~ X ~~SUL~~ - No photo
 47 1 Dash board center ~~cut~~ X ~~SUL~~
 48 1 Dash board beam ~~cut~~ X ~~SUL~~
 49 1 Floor panel repair
 50 1 Floor panel center floor mat X ~~SUL~~

17690

5921

23611

10%

21,249.90

875 917.00
 886.00
 440 597.00
 1420 1,970.00
 2300 5,270.00
 470.00 X
 4,127.00 X
 780.00 X
 217.00 X
 2,351.00 X
 3,177.00 X
 2,416.00 X
 5,790.00 X
 972.00 X
 \$ 74,820.00

S/NO.	QTY	DESCRIPTION	UNIT	\$	AMOUNT \$
SPECIAL NET					
1	1	Windscreen sealant new			
2	1	Radiator coolant new			
3	1	Brake oil new X HN			

160 { \$ 100 200.00
 \$ 60 80.00
 \$ 60.00 X
 \$ 340.00

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT \$
1	1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	900 4,000.00
2	1	To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	1800 3,000.00
3	1	Remove and install front windscreen	250 300.00
4	1	Remove and install dashboard and interior	300 600.00
5	1	Remove and install cooler set	300 600.00
6	1	Reset and rediagram system fault	300 600.00
			\$ 9,100.00

3650

GRAND TOTAL : \$ 84,260.00

ISSUED BY

VERIFIED BY

ESTIMATE CONFIRMED AND ACCEPTED BY

KOH WENG SHENG

KEN TAN

NAME, SIGNATURE, DATE SIGNED

21,249.90
 160.00
 4200.00

25,609.90

20%

20,487.92

4/3-20,500

14 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
 Hp 90010068

14 days

4/3

28/10/2020 @ 1420

Resurvey after repair