

Vehicle Estimate

Supplier: _____
Attention to: _____

Page: 1/1

Vehicle No.:

SLB 5956 G

DETAIL LAB	
Person-in-charge:	
Chassis No.:	
Year:	

Make & Model:

Honda City 1.5A

Parts/Description	Qty	Unit Price (\$)
1 Front LH Fender X Repair	1 pc	420
2 Front Bumper LH Retainer X NN	1 pc	38
3 LH Mirror cover X Repair	1 pc	185
4 LH Mirror Assembly X NN	1 pc	620
5 LH Frt Door Assy. X Repair	1 pc	866
6 LH Rear Door Assy. / Bulb	1 pc	856 ✓
7 LH Rear Window Pwr Motor Unit X NN	1 pc	335
8 LH Side Skirt X Repair	1 pc	1175
9 LH Quarter Panel Assy. X Repair	1 pc	1275
10 Rear Bumper LH Retainer X NN	1 pc	38
11 LH Front Door Seal Set X NN	1 pc	85
12 LH Rear Door Seal Set X NN	1 pc	85
13		
14		-20%: 684.8
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle Estimate

Supplier: _____

Attention to: _____

Page: 4/2

Vehicle No.: _____

DETAIL LAB	
Person-in-charge:	_____
Chassis No.:	_____
Year:	_____

Make & Model:

Honda City
1.5A

Parts/Description	Qty	Unit Price (\$)
1 S/Next		
2 Front Door Panel clips / fasteners X NN	1 set	60.00
3 Rear Door Panel clips / fasteners / etc	1 set	60.00 30
4 Front wheel Arch cowling clip X	1 set	60.00
5 Rear wheel Arch cowling clips X	1 set	60.00
6 Side trim clips fasteners X } NN	1 set	60.00
7		
8		
9		
10		
11		
12		
13		
14 Panel Baring Affected Area	400	1200.00
15 Spray Painting Affected Areas	1100	1600.00
16 Check wiring	30	120.00
17 Removal 2x Door Panels / Pwr Window Modules	60	180.00
18		
19	1590	
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		

4 Days -

2304.8

-20%: 1850

Lump Sum Repair

After repair photos

Gino @ ian

8288 0282

28/10/2020