



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 1979P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	HANDLE BAR	BENT	72.00	72.00
1	SET HANDLE BAR END	CUT	45.00	30.00
1	CLUTCH LEVER	SERVICEABLE	22.00	-
1	BRAKE LEVER	SERVICEABLE	26.00	-
1	SET MIRROR	CUT	94.00	55.00
1	FRONT COWLING	CUT	105.00	105.00
1	FRONT COWLING SCREEN	CUT	60.00	60.00
1	HEADLIGHT COMPLETE	CUT	140.00	140.00
1	HHEADLIGHT MOULD	CUT	36.00	36.00
1	FRONT STAY	SERVICEABLE	53.00	-
2	FRONT SIGNAL LIGHT @\$40.00	CUT	80.00	60.00
2	FORK ASSY @\$246.00	BENT	492.00	290.00
1	FORK UNDER BRACKET	BENT	167.00	167.00
1	FRONT FENDER	GRAZED	76.00	76.00
1	FRONT WHEEL	SERVICEABLE	323.00	-
1	FRONT WHEEL AXLE	SERVICEABLE	29.00	-
2	FRONT FOOTREST @\$45.00	SERVICEABLE	90.00	-
1	EXHAUST MUFFLER COMPLETE	CUT	454.00	454.00
1	MUFFLER PROTECTOR	CUT	53.00	53.00
1	EXHAUST GASKET	SERVICEABLE	17.00	-
	LESS 10% DISCOUNT		-243.40	-159.80
			2,190.60	1,438.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	IU UNIT (SN)	SERVICEABLE	156.00	-
1	SET STEERING CONE & BEARING (SN)	NECESSARY	100.00	80.00
1	SET CRASH BAR (SN)	CUT	300.00	200.00
1	REAR TOP BOX (SN)	BROKEN	220.00	180.00
1	REAR RACK (SN)	SERVICEABLE	150.00	-
			926.00	460.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TOWING FEE.		80.00	35.00
	ALIGN STEERING COMPONENTS.	NOT NECESSARY	100.00	-
	SPRAY PAINTING FOR FRONT COWLING, FENDER, FUEL TANK & COVERS.	NOT NECESSARY	400.00	-
	WORKMANSHIP TO RENEW DAMAGED PARTS.		450.00	250.00
			1,030.00	285.00
	<b>GRAND TOTAL</b>		<b>4,146.60</b>	<b>2,183.20</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,750.00</b>
-----------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS3/III20005668/Gvd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.