



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20005668/Gvd3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 09-11-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1513U	Veh. Inspected	FBF 1979P
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20050048	Excess (\$)	0.00
Assign From	CARINE KHEK	Assign Date	26/10/2020

2. Vehicle Particulars & Condition

Make & Model	BAJAJ PULSAR 200	c.c	199
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	MD2DHJCZZSCC44306	Colour	BLUE
Odometer	5234	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80-17	MAXXIS	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/80-17	BRIDGESTONE	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/05/2020	Inspection Date	12/05/2020
Survey held at	SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------