

## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 11/11/2020 User ID PohSuan

Section A - Accident Details					
Registration Number	SHC4754X				
Case Reference Number	TAX/10/20/2058				
Registration Date	1/4/2016				
Сотрапу Туре	SMRT Taxis Pte Ltd				
Make	ТОУОТА				
Model	PRIUS				
Name of Driver	TAN GEOK SWEE				
Type of Accident	Head to Rear				
Accident Date and Time	27/10/2020 6:30 AM				
Accident Reported Date and Time	27/10/2020 8:55 AM				
Is Surveyor Required?	Yes				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number	24108606				
Special Instruction to ARC,if	REAR PORTION				
Prepared Date and Time	27/10/2020 4:09 PM				
Chassis Number					
Mileage					
Work Shop					
Repair Completion Date and Fime					

	Section B - Summary of Re	epair Estimates
Summary of Repair Estimate	tes	
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$738.00	\$200.00
Total Spare Part Cost	\$2,127.98	\$120.00
Total Other Cost	\$360.00	\$0.00
TOTAL COST	\$3,563.98	\$520.00
Lump Sum Total	\$3,550.00	\$500.00 (L/S)
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / ECICS Limited
ARC / Surveyor Sign Off Date	28/10/2020 5:19 PM	28/10/2020 3:59 PM
Signature		· · · · · · · · · · · · · · · · · · ·
Remarks		L/S, After paint photo.



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592

Estimator Telephone Number 68662623

Accident Reporting Number 68662677

Date Generated : 11/11/2020 User ID PohSuan

Section C - Quotation and Accident Invoice Details							
Quotation Number	QN-2011-0131	Invoice Number					
Quotation Date	11.11.2020	Invoice Date					
nvoice Amount		Prepared Date					

Section D - Details of Repair Estimates							
Part 1 - Labour Works							
Job Scope	Quotation from AR	Adjusted by Surveyor, if					
TO REPAIR REAR PORTION	\$338.00	applicable \$200.00					
Total Labour	\$338.00	\$200.00					

Job Scope	Quotation from ARC	Adjusted by Surveyor, i
TO RESPRAY REAR BUMPER	\$378.00	applicable \$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$738.00	\$200.00

Job Scope	Quotation from ARC	Adjusted by Surveyor, if
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
O WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$0.00

Part Number	Portion	Stock Number	Part Name	Quantity	List Price	Discount	Final Price	Estimator	Surveyor
		52159- 47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Approved Replace	Approved Repair
		90467- 07211	BUMPER CLIPS	0.00	\$2.10	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023- 12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check /
		52016- 47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52016- 47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		89997- 30070	ANTENNA,ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check X
		52576- 47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
~		52575- 47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given χ
		52592- 47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given \
		52591- 47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given
		76088- 47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087- 47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
		76891- 47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Check X
		58308- 47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given
		51442- 12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given X



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63665592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 11/11/2020 User ID PohSuan

			58307- 47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given 🗸
				SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given Y
	Total					\$3,323.90		\$120.00		

Added Spa	Added Spare Parts / Material Usage After Surveyor Signed off								
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount	Final Price	£	Surveyor
Total						1707	141	Check	Check

120.00 -206 -200.00 -200.00 -200.00 -200.00 -200.00