



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLZ374S Mercedes AMG Hybrid CLA180

No	Qty	Parts Description	Estimated Parts Price
1	1	Bumper assy / BR	\$ 2,250.00 1560.41
2	2	Bumper side retainer X svc	\$ 360.00 X
3	2	Bumper side rail / BR (Small)	\$ 260.00
4	2	Bumper mounding / BR (Big)	\$ 340.00
5	1	Bumper sensor middle 1 / Shaded	\$ 250.00
6	1	Bumper sensor middle 2 / Shaded	\$ 250.00
7	1	Bumper lower basic carrier / BR	\$ 950.00
8	1	Front bumper center chrome / BR	\$ 265.00
9	2	Bumper fog lamp X svc	\$ 240.00 X
10	1/2	AMG emblem with switch module / CUT	\$ 550.00
11	1	Tailgate assy / DD	\$ 2,500.00 1681.72
12	1	Tailgate lock / Jammed	\$ 225.00
13	1	Switch sensor with cable X svc	\$ 450.00 X
14	1	Rear end panel / DD	\$ 650.00 541.77
15	1	Rear end top garnish / BR	\$ 325.00
16	1	AMG emblem X nn	\$ 165.85 X
17	1	CLA180 Logo / n/c	\$ 158.36
18	1	Tailgate light (LH) / BR	\$ 780.00
19	1	Tailgate light (RH) X svc	\$ 780.00 X
20	2	Tailgate hinges X svc	\$ 280.00 X
21	2	Tailgate hinges bracket X svc	\$ 220.00 X
22	1	Taillight (LH) / BR	\$ 980.00
23	1	Taillight (RH) X svc	\$ 980.00 X
24	1	Reinforcement / DD	\$ 850.00
25	1	Reinforcement top cover garnish / BR	\$ 365.00
26	1	Exhaust support inner bracket left (Small) / BR	\$ 125.00
27	1	Exhaust support inner bracket right (Small) / BR	\$ 125.00
28	1	Exhaust support bracket big right (Big) / BR	\$ 195.00
29	1	Exhaust support bracket big left X (Big) svc	\$ 195.00 X
30	1	Lower bumper undercarrigate / BR	\$ 550.00
31	1	Rear end gutter panel left X svc	\$ 650.00 X
32	1	Rear end gutter panel right X svc	\$ 650.00 X
33	1	Tailgate inner board X svc	\$ 450.00 X
34	1	Tailgate top cover with light X svc	\$ 325.00 X
Parts sub-total			\$ 18,689.21 11327.26
			10%
			\$ 18,689.21 10194.53



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLZ374S Mercedes AMG Hybrid CLA180

No	Qty	Parts Description	Estimated Parts Price	
<u>Special Nett Items</u>				
1	12	Bumper clips / MC	\$ 60.00	30
2	10	Lower cover clips / MC	\$ 60.00	20
3	10	Insulator clips X nn	\$ 30.00	x
4	6	Tailgate seal clips X nn	\$ 50.00	x
5	8	Support panel garnish clips / MC	\$ 30.00	20
6	1	Number plate with cashing MC / BR	\$ 80.00	40
7	1	Programming / Coding / MC	\$ 500.00	150
Special Nett Items			\$ 810.00	260
Total parts			\$ 19,499.21	



Xin Yun Auto Private Limited
 幸运汽车服务有限公司
 Tel: 6634 0858 Email: xinyunautol@gmail.com
 Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLZ374S Mercedes AMG Hybrid CLA180

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 2,000.00 900
2	To putty and spray painting behind portion.	\$ 1,800.00 660
3	To check wiring and focus behind lights	\$ 1,000.00 30
4	To apply anti rust proofing to front affected area.	\$ 200.00 30
5	To remove and install undercarriage parts.	\$ 150.00 Xnn
6	To balance the wheel.	\$ 80.00 Xnn
7	To conduct wheel alignment.	\$ 120.00 Xnn
8	To remove and install tailgate lock mechanism assy.	\$ 100.00 50
9	To remove and install rear bumper sensor.	\$ 80.00 30
10	To conduct chassis alignment.	\$ 150.00 Xnn
Total labour :		\$ 5,680.00 1700

Total labour : 5,680.00
Total repair cost : 24,369.21

ML PL
24/11/20, 3:30pm
8.5 days
L/S
My AL My

10194.53
 260.00
 1700.00

 12154.53
 20%
 9723.62

L/S - 9,700.00

7 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: