



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS/SMO20011724/R1Uvf3q2

Date: 28/01/2021

Code: SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLD 1099X	Veh. Inspected	SLZ 374S
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2003122	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	28/10/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA180 AMG	c.c	1332
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WDD1183842N032878	Colour	BLUE
Odometer	1323 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	HANKOOK	6 mm
L/H Front Tyre	225/45 R18	HANKOOK	6 mm
R/H Rear Tyre	225/45 R18	HANKOOK	6 mm
L/H Rear Tyre	225/45 R18	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/10/2020	Inspection Date	29/10/2020
Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENEU 6 #01-59 AUTOBAY @ KKAI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**