



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101933

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 24/03/2021
Reference CC3/CTI20011731/Kra3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 9918C
Insured Veh. GBK 573G
Claim No. SNM20D204078/LKKDS
Policy No. DMCVSNA00048312000
Accident Date 23/10/2020
Inspection Date 27/10/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI20011731/Kra3q2	
			Date: 24/03/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 573G	Veh. Inspected	SHD 9918C	
Policy No.	DMCVSNA00048312000	Coverage (\$)	0.00	
Claim No.	SNM20D204078/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	27/10/2020	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC277501	Colour	METALLIC WHITE / RED	
Odometer	356707 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SAILUN	8 mm	
L/H Front Tyre	215/60 R16	SAILUN	8 mm	
R/H Rear Tyre	215/60 R16	FIRENZA	4 mm	
L/H Rear Tyre	215/60 R16	FIRENZA	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/10/2020	Inspection Date	27/10/2020	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9918C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER COVER REAR	BUCKLED	561.70	561.70
1	BUMPER LOWER REAR	SERVICEABLE	411.90	-
1	BUMPER RETAINER RH REAR	DISTORTED	59.80	59.80
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER REFLECTOR RH	SERVICEABLE	16.60	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	547.80	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	114.50	-
1	FENDER PANEL REAR RH	BENT	1,933.20	1,933.20
1	WHEELARCH REAR RH	DISTORTED	275.40	275.40
1	TAILLAMP RH	CRACKED	401.40	401.40
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	FENDER WHEEL HOUSE PANEL REAR RH	TO REPAIR SEE LABOUR	1,933.20	-
	LESS 10% DISCOUNT		-685.35	-323.15
			6,168.15	2,908.35
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	TYRE (30%)(SN)	CUT	250.00	175.00
1	TYRE RIM (SN)	DENTED	300.00	300.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	85.00	66.00
1	SET BUMPER BRACKET SIDE CLIP REAR (SN)	NOT NECESSARY	70.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	75.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	75.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	85.00	-
1	SET TAILLAMP CLIP (SN)	NOT NECESSARY	55.00	-
1	REAR BUMPER PROTECTOR (SN)	NOT NECESSARY	180.00	-
1	SET WHEELARCH CLIP (SN)	NECESSARY	60.00	60.00

Report Ref No. CC3/CTI20011731/Kra3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER SCREW (SN)	NOT NECESSARY	60.00	-
1	FENDER NUT (SN)	NOT NECESSARY	60.00	-
			2,055.00	601.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	440.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR,BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,TAILLAMP PANEL LH AND FENDER WHEEL HOUSE PANEL REAR RH.		1,200.00	600.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		250.00	30.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
			2,990.00	1,150.00
GRAND TOTAL			11,213.15	4,659.35

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,750.00
---	--	--	-----------------

Report Ref No. CC3/CTI20011731/Kra3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 9918C

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

