

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9918C**AAD2010-108***Not Authorised**61 Day @ 365cph*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 OCT 2020**SHD9918C**

VF1ABL15AUC277501

RENAULT

LATITUDE

23/10/2020

CHINA

5/6/2014

PART		LIST	
1 BUMPER COVER REAR	\$	Bu 561.70	✓
1 BUMPER LOWER REAR	\$	Sn 411.90	X
1 BUMPER RETAINER RH REAR	\$	DIY 59.80	✓
1 BUMPER BRACKET SIDE RH REAR	\$	Sn 82.10	X
1 BUMPER REFLECTOR RH	\$	Sn 16.60	X
1 BUMPER BEAM REAR	\$	R 547.80	X
1 BUMPER BEAM BRACKET LH REAR	\$	R 114.50	X
1 BUMPER BEAM BRACKET RH REAR	\$	R 114.50	X
1 FENDER PANEL REAR RH	\$	R 1,933.20	✓
1 WHEELARCH REAR RH	\$	DIY 275.40	✓
1 TAILLAMP RH	\$	CM 401.40	✓
1 TAILLAMP PANEL LH	\$	R 401.40	X
1 FENDER WHEEL HOUSE PANEL REAR RH	\$	R 1,933.20	X
TOTAL	\$	6,853.50	
10%	\$	685.35	
	\$	6,168.15	

Special Nett

1SET PARKING AID	\$	Sn 700.00	X
1 TYRE	\$	755 Sn 250.00	302 Sn
1 TYRE RIM	\$	R 300.00	✓
1SET REAR BUMPER CLIP	\$	R 85.00	68 Sn
1SET BUMPER BRACKET SIDE CLIP REAR	\$	R 70.00	X
1SET REAR BUMPER RETAINER CLIP	\$	R 75.00	X
1SET BUMPER LOWER REAR RIVET	\$	R 75.00	X
1SET BUMPER LOWER REAR CLIP	\$	R 85.00	X

Trans-cab Auto Services Pte Ltd

AAD2010-108

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9918C**1SET TAILLAMP CLIP**

1 Rear Bumper Protector

1SET WHEELARCH CLIP

1 FENDER SCREW

1 FENDER NUT

\$	55.00	X
\$	180.00	X
\$	60.00	✓
\$	60.00	X
\$	60.00	X
TOTAL	\$ 1,935.00	

TOTAL PARTS \$ 8,103.15**LABOUR**

Putty And Spray Painting Of The Affected Portion.

\$ 1,200.00 4401

To reinstall rear bumper parking sensor.

\$ 170.00 601

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 1,200.00 6001

To Rust-Proofing and apply undercoat Of The Affected
Areas.

\$ 250.00 301

To Check Electrical Lighting Concerned.

\$ 170.00 201

TOTAL \$ 2,990.00**Over All Total \$ 11,093.15****(LUMP SUM) Repair Days****20 DAYS**

4 days

For Official Use

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: