

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9918C**AAD2010-108***Not Authored*
6/1/2020

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 OCT 2020**SHD9918C**

VF1ABL15AUC277501

RENAULT

LATTITUDE

23/10/2020

CHINA

5/6/2014

PART

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER REFLECTOR RH
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 FENDER PANEL REAR RH
- 1 WHEELARCH REAR RH
- 1 TAILLAMP RH
- 1 TAILLAMP PANEL LH
- 1 FENDER WHEEL HOUSE PANEL REAR RH

LIST

\$	<i>Bu</i>	561.70	✓
\$	<i>SL</i>	411.90	X
\$	<i>DI</i>	59.80	✓
\$	<i>SL</i>	82.10	X
\$	<i>SL</i>	16.60	X
\$	<i>RL</i>	547.80	X
\$	<i>RL</i>	114.50	X
\$	<i>RL</i>	114.50	X
\$	<i>RL</i>	1,933.20	✓
\$	<i>DI</i>	275.40	✓
\$	<i>CM</i>	401.40	✓
\$	<i>RL</i>	401.40	X
\$	<i>RL</i>	1,933.20	X
TOTAL	\$	6,853.50	
10%	\$	685.35	
	\$	6,168.15	

Special Nett

- 1SET PARKING AID
- 1 TYRE
- 1 TYRE RIM
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET SIDE CLIP REAR
- 1SET REAR BUMPER RETAINER CLIP
- 1SET BUMPER LOWER REAR RIVET
- 1SET BUMPER LOWER REAR CLIP

\$	<i>SL</i>	700.00	X
\$	<i>CU</i>	250.00	<i>302.50</i>
\$	<i>RL</i>	300.00	✓
\$	<i>RL</i>	85.00	<i>66.50</i>
\$	<i>RL</i>	70.00	X
\$	<i>RL</i>	75.00	X
\$	<i>RL</i>	75.00	X
\$	<i>RL</i>	85.00	X

Trans-cab Auto Services Pte Ltd**AAD2010-108**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9918C

1SET TAILLAMP CLIP	\$	nn	55.00	X
1 Rear Bumper Protector	\$	nn	180.00	X
1SET WHEELARCH CLIP	\$	nn	60.00	✓
1 FENDER SCREW	\$	nn	60.00	X
1 FENDER NUT	\$	nn	60.00	X
TOTAL	\$		1,935.00	

TOTAL PARTS	\$	8,103.15
--------------------	-----------	-----------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	1,200.00	4401
To reinstall rear bumper parking sensor.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,200.00	6001
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
To Check Electrical Lighting Concerned.	\$	170.00	201
TOTAL	\$	2,990.00	
Over All Total	\$	11,093.15	

(LUMP SUM) Repair Days~~20~~ DAYS

4 days

For Official Use

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9918C

AAD2010-108

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)