

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

PC 3457R
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/WL

Claim Type: Third Party

Accident Date: 27/10/2020

TP Veh Reg No: SMH4348A

Estimate No: ES2090894/WL

Date: 09 Nov 2020

Policy No: 20-MK000283-R01

Veh Reg No: PC3457P

Make/Model: TOYOTA TOYOTA
HIACE 3.0 DX DIESEL

Chassis No: KD2010145702

Engine No: 1KD2424436

Reg. Date: 14/03/2015

Not Authorized

11 Lng &

Runway After Paint

3 days

Estimate Repair Cost to Vehicle No :PC3457P

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	495.10	1 PC	495.10	✓
2 REAR BUMPER LH SIDE RETAINER	40.40	1 PC	40.40	✓
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
4 LH TAILLAMP	213.80	1 PC	213.80	✓
			770.30	
		Less 25%	192.58	577.73
Labour				
5 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, KNOCK & REPAIR REAR LH SIDE PANEL & REALIGN THE SAME	450.00	1 LA	450.00	400
6 PUTTY & RESPRAY ON REAR LH SIDE PANEL	400.00	1 LA	400.00	360
7 REMOVE & REFIX REVERSE SENSORS & CHECK SYSTEM	40.00	1 LA	40.00	✓
			890.00	890.00

Total S\$ 1,467.73

Add GST @ 7% 102.74

Total Amount Payable S\$ 1,570.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE