



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2008225
INV Date 10/12/2020
Reference CC4/FCI20011735/Kes3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SJV 3864U
Insured Veh. SHD 8643B
Claim No. D20004365MFSH/1
Policy No. D-20094921MFSH
Accident Date 26/10/2020
Inspection Date 28/10/2020

Description	Total
Survey Inspection	598.00
Digital Photographs	
Transportation	
Less: Discount	-18.00
Subtotal	580.00
GST (7%)	40.60
Grand Total	620.60

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



Your Ref : D20004365MFSH/1

Date: 10th Dec 2020

Our Ref : CC4/FCI20011735/Kes3q2

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

Singapore 068877

(The Motor Claims Department)

Attn: Jas Tan

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJV 3864U
INSURED VEHICLE SHD 8643B ACCIDENT ON 26/10/2020**

Instruction was received to inspect the vehicle Reg. No. SJV 3864U. The inspection was conducted on 28/10/2019 at the premises of M/s Ngiak motor works, No. 10 kaki bukit road 2 first east centre #03-36, Singapore 417868.

The following vehicle information was recorded:

Registration Number	: SJV 3864U
Make/Model	: Honda Civic Ima 1.3L CVT
Year of Registration	: 2010
Body Colour	: Metallic Dark Blue
Chassis Number	: JHMFD36209S202236
Engine Capacity	: 1339 cc
Speedometer Reading	: 318023 km

The vehicle sustained damages at the rear o/s and front portion. The Estimated repair cost of such vehicle is S\$19,284.16 (Sin Dollars: Nineteen Thousand Two Hundred Eighty four and sixteen cents only.) (Exclude check items S\$7,625.44 Nett) (Details see photographs enclosed)

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"uneconomical Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 30,000.00

Less: LTA Reimbursement Value (RV)

(S\$ 13,678.00)

Nett Liability

S\$ 16,322.00

S\$ 16,322.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 19,284.16

(Exclude check items S\$7,625.44Nett)

Nett Liability

S\$ 19,284.16

(a) – (b) =

(S\$ 2,962.16)

The amount of estimated saving of S\$2,962.16 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



KONG SENG CHEONG

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),

MASME(USA), B Bus(Aust), MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),

AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 3864U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

