

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/SMO20011737/Ktd3e2 SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND Date: 10-11-2020 **TOWER SINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. FBA 9656U Veh. Inspected **GBK 2901E** Policy No. Coverage (\$) 0.00 CMTD2003142/AGC Excess (\$) 0.00 Claim No. **Assign From GRACE TEO** 28/10/2020 **Assign Date** 2. **Vehicle Particulars & Condition** Make & Model NISSAN NV200 1597 c.c **Engine No. HIDDEN** Year of Reg. 2020 VM20141252 Chassis No. Colour **BLACK** 25216 KM Odometer **IN ORDER** Steering **IN ORDER** Brakes Modification NIL GOOD General **Conditions of Tyres** 3. Size Make **Balance** TOYO 5 mm 165/80 R14 R/H Front Tyre 165/80 R14 TOYO L/H Front Tyre 5 mm R/H Rear Tyre 165/80 R14 TOYO 9 mm 165/80 R14 TOYO 9 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. **General Information** 5. 27/10/2020 Inspect Date / Time 28/10/2020 (03:10 PM) **Accident Date** Survey held at TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$5,000

Report Ref No. CS3/SMO20011737/Ktd3e2

Estimate Days of Repair

Inspected By

5b.

KONG SENG CHEONG

Licensed Appraiser

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.