

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	Oct 002/2020
Date	26/10/2020
Vehicle No	SMP7466E
Make / Model	Honda Shuttle

Cecilia

To: M/s China Taiping Insurance (S) Pte Ltd
Address: 3 Anson Rd, #16-00 Springleaf Tower, 079909

GP72004063

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	rear bumper Defend		\$ 1,385.00
1 set	rear bumper clip		\$ 30.00
1 pc	o/s rear bumper side retainer		\$ 38.00
1 set	rear reverse sensor		\$ 200.00
1 pc	o/s rear bumper reflector	1303	\$ 75.00
1 pc	o/s rear bumper reflector garnish Defend	1042.40	\$ 85.00
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 400.00
2	to putty and spray painting on affected area		\$ 500.00
3	anti rust	440	\$ 80.00
4	wiring check		\$ 30.00
5	R&R reverse sensor		\$ 40.00
	Subtotal:		\$ 2,863.00

BEST SOLUTION AUTOCARE PTE LTD

Authorised Signature

Adrian Ling.
1/s 28/10/20-
03 days.

total: 1482.40
1/s: 1.1K.