



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd.	Cust No/Name /Chin Leong Yong
MOTOR CLAIM DEPARTMENT	Reg No/Reg Date SDK6168E / 27/05/201
78 SHENTON WAY #08-16	Date In/Mileage 28/10/2020/ 0
AIG BUILDING	Chassis No KNAFZ411MG5570090
SINGAPORE 079120	Engine No G4FGFH608138
Contact No 64191000	Make/Model KIA/FORTE K3 1.6 A SX ADQ
	Colour/Trim D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/10/2020/ 13:59	QUK	282 / Kevin Leong	23435
Description of Goods / Services					
			Qty	Unit Price	Disc% Amount
E PNT88000	TO REPLACE REAR BUMPER, REAR RH FENDER, REAR RH DOOR, FRT RH DOOR & @400 X 5				2000 2800.00
	AFFECTED AREA				
	TO REPAIR ON FRT RH FENDER & RH B-PILLAR				
E PNT98000	PAINT WORK ON REAR BUMPER, REAR RH FENDER, REAR RH DOOR, FRT RH DOOR, FRT RH DOOR, @350 X 5.5				1925 2450.00
	FRT RH FENDER, RH B-PILLAR & RH WING MIRROR COVER				
E PNT88000	TO REMOVE & INSTALL REAR PARKING ASSIST				100 120.00
E PNT88000	TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW-PANEL				120.00
E PNT88000	TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL				X 120.00
E PNT88000	TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				120.00
E PNT88000	TO REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR				120.00
M SUNDRY	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR				240.00
	TO APLY WINDSCREEN SEALANT				80.00
A WHEELALIGNMENTBP	To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY	TO TRANSFER REAR RH RIM INCLUDING BALANCING				30 50.00
M SUNDRY	TO APPLY SEALANT ON AFFECTED AREA				40 120.00
M SUNDRY	PERFORM RUST PREVENTION				80 120.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICALSYSTEM				30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				120.00

SURVEYOR NAME: Ram-4p2000068SURVEYOR SIGNATURE: RyDATE: 28/10/2020 1700REMARKS: 16 dayRevers / excess: THNRevers before print

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

GST Reg No : MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd.		Cust No/Name	/Chin Leong Yong
MOTOR CLAIM DEPARTMENT		Reg No/Reg Date	SDK6168E / 27/05/201
78 SHENTON WAY #08-16		Date In/Mileage	28/10/2020/ 0
AIG BUILDING		Chassis No	KNAFZ411MG5570090
SINGAPORE 079120		Engine No	G4FGFH608138
Contact No 64191000		Make/Model	KIA/FORTE K3 1.6 A SX ADQ
		Colour/Trim	D7U / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/10/2020/ 13:59	QUK	282 / Kevin Leong	23435
Description of Goods / Services					
				Qty	Unit Price Disc% Amount
USING HI-SCAN PRO TEST					
M SUNDRY					20 50.00
SUNDRIES					
M LAMP ASSY-REAR COMBINATION, RH CM				1.00	843.00 20.00 674.40
M WHEEL ASSY-ALUMINIUM SC				1.00	958.00 20.00 766.40
M PANEL ASSY-QUARTER OUTER, RH BUC				1.00	1213.00 20.00 970.40
M PANEL ASSY-RR COMB LAMP HSG, RH ? XSR				1.00	123.00 20.00 98.40
M PANEL ASSY-REAR DOOR, RH BUC				1.00	1361.00 20.00 1088.80
M PANEL ASSY-FRONT DOOR, RH BUC				1.00	1542.00 20.00 1233.60
M FILM-ANTI CHIPPNG RH ? NE				1.00	27.00 20.00 21.60
M HANDLE ASSY-DOOR OUTSIDE SC				1.00	214.00 20.00 171.20
M BASE ASSY-FR DR O/S HANDLE RH ? XSR				1.00	52.00 20.00 41.60
M LATCH ASSY-FRONT DOOR, RH ? XSR				1.00	253.00 20.00 202.40
M W/STRIP-RR DR BODY SIDE RH ? XSR				1.00	103.00 20.00 82.40
M W/STRIP ASSY-RR DR SIDE RH ? XSR				1.00	114.00 20.00 91.20
M W/STRIP ASSY-RR DR BELT O/S RH ? XSR				1.00	89.00 20.00 71.20
M W/STRIP-FR DR BODY SIDE RH ? XSR				1.00	94.00 20.00 75.20
M W/STRIP ASSY-FR DR SIDE RH ? XSR				1.00	122.00 20.00 97.60
M W/STRIP ASSY-FR DR BELT O/S RH ? XSR				1.00	58.00 20.00 46.40
M GUARD ASSY-REAR WHEEL, RH ? XSR				1.00	75.00 20.00 60.00
M GLASS ASSY-REAR WINDOW ? XSR				1.00	534.00 20.00 427.20
M MOULDING-REAR WINDOW GLASS NE				1.00	27.00 20.00 21.60
M STOPPER-RR WINDOW GLASS NE				2.00	4.00 20.00 6.40
M PAD-WINDSHIELD GLASS NE				8.00	2.00 20.00 12.80
M BLACK TAPE-FR DR FRAME UP, RH NE				1.00	13.00 20.00 10.40
M BLACK TAPE-RR DR FRAME UP, RH NE				1.00	11.00 20.00 8.80
M TAPE-RR DR FRAME BLACK RR, RH NE				1.00	8.00 20.00 6.40
M BLACK TAPE-FR DR RR, RH NE				1.00	12.00 20.00 9.60
M COVER-RR BUMPER SC				1.00	791.00 20.00 632.80
M COVER-RR BUMPER, UP ? XSR				1.00	245.00 20.00 196.00
M BRACKET-RR BUMPER SIDE MTG, RH ? XSR				1.00	33.00 20.00 26.40
M MIRROR ASSY-OUTSIDE RR VIEW, RH CM				1.00	685.00 20.00 548.00

Confirm & accepted by

Authorized signatory and company stamp

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

15,116.80

Nett
14,479.20
1013.54

7% GST on

14479.20

Total Payable 15,492.74

Validity of this estimate is 14 days from date of quote/estimate generated by Repai

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.