

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0802/2020/NS
DATE : 26-Oct-20
WIP : 54468

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

3 days - ok - Jy - 10 Feb 20

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS CHAO LYNNE MAREE @ BEASLEY LYNNE MAREE
ADDRESS : 335 BUKIT TIMAH ROAD
#28-01
SINGAPORE 259718
TELEPHONE : HP +65 81510637
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800142787-01
VEHICLE NO : **SMG 2416 E**
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 11/12/2018
ENGINE NO : CVK 073152
CHASSIS NO : WAUZZZGAXJA050672
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Oct-20
PLACE OF ACCIDENT : AYE(JUST BEFORE NORMANTAN PARK EXIT 7A)

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 2416 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N	\$ 280.00		
2	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM TO FACILITATE RENEWAL OF RHS FRONT DOOR WINDOW GLASS AND RHS WING MIRROR ASSY.	S/N	\$ 400.00	\$	260.00
3	TO INSTALL SOLAR FILM FOR RHS FRONT DOOR WINDOW GLASS.	S/N	\$ 400.00		
4	TO DISMANTLE AND RENEW RHS FRONT DOOR. TO REPAIR RHS UPPER A-PILLAR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,600.00	\$	250.00
5	TO RESPRAY RHS FRONT DOOR, RHS FRONT FENDER, RHS UPPER A-PILLAR, DOOR HANDLE AND RHS WING MIRROR COVER.		\$ 3,500.00	\$	700.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,372.00	\$	1,402.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 2416 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT DOOR - RH		\$ 3,091.00	
2	FRONT DOOR OUTER SEAL	NEC	\$ 220.00	
3	BONDING AGENT	NEC	\$ 47.00	
4	CLEANING SOLUTION	NEC	\$ 65.00	
5	FRONT DOOR CATCH		\$ 119.00	
6	DOOR HANDLE TRIM PLATE		\$ 87.00	
7	DOOR HANDLE TRIM - RH		\$ 135.00	
8	EXTERIOR MIRROR MOUNTING - RH		\$ 1,077.00	\$ 861.60
9	MIRROR CAP - RH		\$ 261.00	\$ 208.80
10	MIRROR GLASS - RH		\$ 1,649.00	
11	ROOF MOULDING - RH		\$ 622.00	
12	WINDOW SLOT SEAL - RH		\$ 394.00	
13	CORNER TRIM - RH		\$ 45.00	
14	FRONT DOOR WINDOW - RH		\$ 286.00	
15	DOOR TRIM - RH		\$ 157.00	\$ 125.60
16	FENDER TRIM - RH		\$ 157.00	
17	TYRE PRESSURE DATA PLATE		\$ 36.00	
18	WATER DEFLECTOR STRIP		\$ 66.00	
19	SUNDRIES		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 8,814.00	\$ 1,196.00
TOTAL LABOUR CHARGES		:	\$ 6,372.00	\$ 1,402.00
GRAND TOTAL		:	\$ 15,186.00	\$ 2,598.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-04/12/20

