

FBP 5057S

To wing — \$35 —

To wing to idac — \$35 —

Front Mudget — \$76 cut —

Front Fork R/L — \$380 . SN/120

Under Bracket — \$195 . xXnn

Front Spoling^{rim} — \$245 del —

Front Brake disc — \$135 bt —

Front Central Cover \$125 cut — ^{mm} ✓

R/L Front Signal — \$96 . ^{mm} ✓

Front No plate — \$25 . bt —

R/L Front Side Failing — \$170 . cut —

Front Head light \$98 . ^{mm} ✓

Head Cowing — \$85 . ^{mm} ✓

Head Cowing^{windscreen} wiskin — \$38 . ^{mm} ✓

Headle Bar 1pc — \$98 . ?

Headle Grip R/L \$60 . del —

MIRPLE R/L — \$50 . cut ✓

金国摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

Motor Assy — \$295.00 —

Brake Pump Assy — \$145.00 — *given inside*

Body Central Big Cover — \$165.00 —

Front Foot Rest Bar Assy — \$70.00 —

AIR PIPE Assy — \$295.00 —

(R) Rear Side Failing — \$125.00 —

(L) Rear Foot Rest Bar — \$70.00 —

(L) Rear Foot Rest — \$30.00 —

E33 - Rear Civi Box — \$165.00 —

2623 Rear Civi Box Bracket — \$135.00 —

10% 2360.70

390

Rear No Plate — \$20.00 —

2750.70 Labour — \$280.00 — 200.

Tanaka 97445745
int' 29/10/2002 4:15pm

\$3791

Lump sum

Pay. after repair

tanaka@lumpsum.com

5 days

1/s \$2200

5 days

金国摩托私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101

LKK Auto Consultants hence notify Tel: 6265 0226 Fax: 6265 2588

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company