

HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE

50, Bukit Batok Street 23,

#02-02, Midview Building,

Singapore 659578

Tel: 68966619 Fax: 62678616

Email: huachinmotor@singnet.com.sg

BIKE NO: FBM652B YAMAHA SNIPER T150

S/N	DESCRIPTION/ MATERAIL	Quotation
1	MIRROR <i>scr</i>	\$ 60.00
2	BRAKE LEVER <i>scr</i>	\$ 40.00
3	CLUTCH LEVER <i>X</i>	\$ 40.00 <i>X</i>
4	BALANCER <i>scr</i>	\$ 45.00
5	COVER SET <i>cut</i>	\$ 550.00
6	PIPE PROCTETOR <i>scr</i>	<i>995</i> \$ 75.00
7	BOX <i>scr</i>	<i>10%</i> \$ 180.00 <i>150 s/n</i>
8	INSIDE COWLING <i>scr</i>	\$ 60.00
9	HANDLE BAR <i>X</i>	<i>895.50</i> \$ 85.00 <i>X</i>
10	FOOTREST <i>scr</i>	\$ 75.00
11	BRAKE PEDAL <i>scr</i>	\$ 60.00
12	HANDLE GRID <i>scr</i>	\$ 30.00
13	RIM <i>repair</i>	<i>S/N-150</i> \$ 450.00 <i>Labour - 100</i>
14	MUDGUARD <i>repair</i>	\$ 60.00 <i>XR</i>
TOTAL		\$ 1,810.00
(LESS 10% DISCOUNT)		-\$ 181.00
		\$ 1,629.00
PLUSS 7% GST		\$ 114.03
		\$ 1,743.03
Add special nett items from above		
15	NO PLATE (REAR) <i>bt</i>	\$ 20.00
16	TOWING <i>X</i>	\$ 60.00 <i>X</i>
17X	LABOUR CHARGE	\$ 400.00 <i>250</i>
Lump sum repair adjustment		\$ 2,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

4 days

L/S

29/10/20 @ 1145

Resurvey after repair

895.50

150.00

370.00

1415.50

20%

1132.40

4/5 - \$1,150