

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SKF8198Z
MODEL : HYUNDAI VELOSTER
DATE OF ACCIDENT : 27.10.20
TIME OF ACCIDENT : 13:15HRS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

DATE : 27.10.20

Signature:
Date:

KMH TC 610VC408176
Jasper

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Deland</i>	1	\$ 575.70	\$ 575.70
2	FRONT BUMPER LOWER GRILLE <i>cracked.</i>	1	\$ 107.70	\$ 107.70
3	FRONT BUMPER UPPER GRILLE C/W LOGO <i>crackd.</i>	1	\$ 167.90	\$ 167.90
4	FRONT BUMPER FOG LAMP <i>new</i>	2	\$ 189.40	\$ 378.80
5	FRONT BUMPER LOWER BEAM <i>new</i>	1	\$ 147.10	\$ 147.10
6	FRONT BUMPER NUMBER PLATE HOLDER <i>set</i>	1	\$ 87.90	\$ 87.90
7	FRONT BUMPER TOWING HOOD <i>new</i>	2	\$ 19.20	\$ 38.40
8	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 34.20	\$ 68.40
9	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 410.50	\$ 410.50
10	FRONT BUMPER REINFORCEMENT SPONGE <i>crackd.</i>	1	\$ 110.70	\$ 110.70
11	FRONT BUMPER ENGINE UNDER COVER <i>new</i>	1	\$ 127.40	\$ 127.40
12	HEADLAMP (LED) <i>RH crackd</i>	2	\$ 2,234.60	\$ 4,469.20
13	HEADLAMP LOWER BRACKET <i>new</i>	2	\$ 39.10	\$ 78.20
14	FRONT FENDER COWLING <i>new</i>	2	\$ 106.60	\$ 213.20
15	FRONT SUPPORT TOP PANEL <i>new</i>	1	\$ 217.40	\$ 217.40
16	HORN <i>new</i>	2	\$ 78.30	\$ 156.60
17	AIRCON CONDENSOR AIR GUARD <i>new</i>	1	\$ 28.40	\$ 28.40
18	REAR BUMPER <i>Deland</i>	1	\$ 537.70	\$ 537.70
19	REAR BUMPER BRACKET <i>new</i>	5	\$ 77.10	\$ 385.50
20	REAR BUMPER (LOWER) <i>Deland</i>	1	\$ 284.50	\$ 284.50
21	REAR BUMPER LAMP <i>new</i>	2	\$ 130.70	\$ 261.40
22	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 39.20	\$ 78.40
23	REAR BUMPER REINFORCEMENT <i>crackd</i>	1	\$ 672.60	\$ 672.60
24	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 29.20	\$ 58.40
25	REAR NUMBER PLATE LAMP <i>new</i>	2	\$ 67.10	\$ 134.20
26	TAIL LAMP <i>new</i>	2	\$ 1,108.50	\$ 2,217.00
27	REAR FENDER INNER COWLING <i>new</i>	2	\$ 96.30	\$ 192.60
28	REAR FENDER INNER TRIM <i>new</i>	2	\$ 236.30	\$ 472.60
29	TAILGATE INNER LOCK <i>new</i>	1	\$ 148.40	\$ 148.40

2234.60

612.60

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SKR7485M
 MODEL : HYUNDAI VELOSTER
 DATE OF ACCIDENT : 27.10.20
 TIME OF ACCIDENT : 13:15HRS

30	TAILGATE LOCK BOTTOM <i>Not New</i>	1	\$ 21.30	\$ 21.30	+
31	TAILGATE DETECTOR <i>Ne n</i>	1	\$ 169.10	\$ 169.10	+
32	TAILGATE WEATHER STRIP <i>Ne n</i>	1	\$ 138.70	\$ 138.70	+
33	REAR END PANEL <i>Dented</i>	1	\$ 499.30	\$ 499.30	✓
34	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 97.40	\$ 97.40	✓
35	REAR FLOOR PANEL <i>Ne n</i>	1	\$ 966.80	\$ 966.80	+
36	REAR FLOOR TOP BOARD <i>Ne n</i>	1	\$ 187.10	\$ 187.10	+
37	REAR SPARE TYRE BOLT <i>Ne n</i>	1	\$ 24.00	\$ 24.00	+
38	REAR TOOLS SPONGE <i>2</i>	1	\$ 126.10	\$ 126.10	+
39	REAR EXHAUST PIPE	1	\$ 1,446.20	\$ 1,446.20	+
40	REAR EXHAUST CHROME PIPE <i>Not New</i>	1	\$ 304.40	\$ 304.40	+
41	REAR EXHAUST INSULATOR	1	\$ 260.10	\$ 260.10	+
42	REAR EXHAUST MOUNTING	4	\$ 29.20	\$ 116.80	+
43	REAR REVERSE SENSOR <i>2 pieces d. d.</i>	4	\$ 178.20	\$ 712.80	356.40.
44	REAR REVERSE SENSOR HOLDER <i>2 pieces</i>	4	\$ 42.60	\$ 170.40	85.20.

590440.
 4723.52

TOTAL PRICE \$ 18,067.30
 LESS 20% \$ 3,613.46
 SUB TOTAL PRICE \$ 14,453.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00	30.
2	FRONT BUMPER CLIP (SET) <i>Ne n</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT FENDER COWLING CLIP (SET) <i>3rd</i>	1	\$ 80.00	\$ 80.00	+
4	FRONT SUPPORT TOP PANEL SEALANT	1	\$ 120.00	\$ 120.00	+
5	COOLANT <i>Not New</i>	1	\$ 80.00	\$ 80.00	+
6	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00	60.
7	REAR BUMPER CLIP (SET) <i>Ne n</i>	1	\$ 80.00	\$ 80.00	30.
8	TAILGATE INNER LOWER TRIM CLIP (SET) <i>Not New</i>	1	\$ 80.00	\$ 80.00	+
9	TAILLAMP CLIP (SET) <i>Ne n</i>	1	\$ 30.00	\$ 30.00	+
10	REAR FENDER INNER TRIM CLIP (SET) <i>3rd</i>	1	\$ 80.00	\$ 80.00	+
11	REAR FENDER INNER COWLING CLIP (SET) <i>Ne n</i>	1	\$ 80.00	\$ 80.00	+
12	REAR END PANEL INSULATION SEAL <i>Ne n</i>	1	\$ 150.00	\$ 150.00	60
13	REAR END PANEL TOP GARNISH CLIP (SET) <i>Ne n</i>	1	\$ 50.00	\$ 50.00	20
14	REAR FLOOR PANEL INSULATION SEAL <i>Not New</i>	1	\$ 450.00	\$ 450.00	X
15	TRIANGLE BREAKDOWN SIGN <i>Not New</i>	1	\$ 180.00	\$ 180.00	X

TOTAL \$ 1,700.00

230

TO : **AXA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SKR7485M**
 MODEL : **HYUNDAI VELOSTER**
 DATE OF ACCIDENT : 27.10.20
 TIME OF ACCIDENT : 13:15HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,000.00	300
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	250
3	REFOCUS HEADLAMP BEAM	\$ 80.00	x
4	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

550

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	600
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
8	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x

1400

TOTAL \$ 6,220.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 16,153.84
 TOTAL LABOUR COST : \$ 6,220.00
 TOTAL REPAIR COST : \$ 22,373.84

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian
 4/5 28/10/20

06 Days

total: 6903.52

4/5: 5.5K