

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Accident Date : 25.10.2020

Not Authorized
11 Day @ 5000/- Max
Running After Rain
6 days

Policy No: **Third Party**

Date: **28.10.2020**

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Stream" Reg. No. SLH5515P Claiming Against Your Insured Reg. No. SLA6669J			
1pc	Tailgate		<i>B7</i> 956.00 ✓
1pc	Tailgate Glass Moulding		<i>Not Return</i> 57.00 ✓
1pc	Tailgate Lock		<i>JAM</i> 115.00 <i>507m</i>
1pc	Tailgate Weatherstrip		<i>Not Return</i> 128.70 <i>507m</i>
1pc	Tailgate Trim Board		<i>my dit</i> 150.00 ✓
12pcs	Tailgate Trim Board Clips	3.80	<i>na</i> 45.60 ✓
1pc	Tailgate Inner Handle Grip		<i>mir</i> 26.00 ✓
1pc	Tailgate Stopper RH		<i>mir</i> 8.90 ✓
2pcs	Taillamps	489.20	<i>MSCM</i> 978.40 ✓
1pc	Rear Bumper		<i>B7</i> 599.00 ✓
2pcs	Rear Bumper Brackets	15.50	<i>R</i> 31.00 X
12pcs	Rear Bumper Clips	3.80	<i>na</i> 45.60 ✓
1pc	Rear Bumper Tow Cover		<i>mir</i> 14.20 ✓
1pc	End Panel		<i>B7</i> 325.00 ✓
1pc	End Panel Inner Panel		<i>B7</i> 472.00 ✓
1pc	End Panel Garnish		<i>my cut</i> 123.00 ✓
1pc	End Panel Garnish Center Jack Cover		<i>dit</i> 145.20 ✓
1pc	Rear Tyre Jack		<i>R</i> 132.00 2 X
1pc	Rear Fender Trim Board		<i>CMT</i> 297.40 ✓
1pc	Spare Tyre Panel		<i>R</i> 1,062.60 X
1pc	Spare Tyre Panel Insulation		<i>na</i> 190.00 <i>605m</i>
2pcs	Rear Trunk Spare Top Boards	130.40	<i>Not</i> 260.80 ✓
1pc	Rear Exhaust Silencer		<i>R</i> 780.00 X
1pc	Rear Exhaust Silencer Gasket		<i>in</i> 18.20 X
	Less 20%		6,961.60 1,392.32 5,569.28
	Tailgate Glass Sealant		<i>na</i> 405m 50.00 SN
	Tailgate Glass Sealer		<i>na</i> ✓ 30.00 SN
	Tailgate Glass Fastener		<i>na</i> 305m 50.00 SN
	Tailgate Emblem Sticker		<i>na</i> 55.00 SN X
	Rear Number Plate		<i>Not</i> 45.00 SN ✓
	Rear Bumper Reverse Sensor		<i>Not</i> 2005m 280.00 SN ✓
	Rear Reverse Camera		<i>Not</i> 250.00 SN ✓
	In Car Dash Camera (Front & Rear Type)		<i>in</i> 750.00 SN X
		C/F	6,329.28

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **28.10.2020**

Accident Date : 25.10.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Honda Stream" Reg. No. SLH5515P Claiming Against Your Insured Reg. No. SLA6669J		
		B/F	6,329.28
	To Dismantle / Transfer Tailgate Fittings / Ancillary Accessories		150.00 <i>601</i>
	To Dismantle / Refit Tailgate Glass		160.00 <i>1201</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims		80.00 <i>601</i>
	To Conduct Electrical Check, Replace Reverse Camera, Sensors, Module, Rewiring etc.		120.00 <i>601</i>
	To Supply Rear Body Panel Sealant		80.00 <i>301</i>
	To Dismantle / Refit Rear Boot Spoiler. Supply Adhesive, Double Sided Tape, Drilling Etc.		90.00 <i>501</i>
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replace / Repair Panel		100.00 <i>601</i>
	To Dismantle / Repair Exhaust Silencer		100.00 <i>601</i>
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Floor Panel etc. Cnt, Weld End Panel and Parts Replacement		1,500.00 <i>9001</i>
	To Respray Affected Areas		1,000.00 <i>8001</i>
		Total :	9,709.28

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: