

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31494

Date : 28-Oct-2020

PAGE : 1

Vehicle Insured : YN 8896 J
Accident Date : 26-Oct-2020

Our Ref : 020513 (CHINA) / QUEK

MR AW KAI KIAT
Singapore

Not Authorized
@ 4178.72

Running After Paint

4 days

ESTIMATED COST OF REPAIR FOR HONDA VEZEL 1.5X CVT (2015) SKX2642C

1 pc rear bumper		<i>nd/ht</i> 459.80	
2 pcs rear bumper side retainer (LH/RH)	@ S\$ 17.50	<i>in</i> 35.00	X
2 pcs rear bumper side cover (LH/RH)	@ S\$195.00	<i>in</i> 390.00	X
10 pcs rear bumper clips	@ S\$ 3.50	<i>in</i> 35.00	X
2 pcs rear wheel arch garnish (LH/RH)	@ S\$150.00	<i>in</i> 300.00	X
1 pc rear end panel		<i>in</i> 411.90	X
1 pc rear end panel top garnish		<i>in</i> 92.30	X
1 pc tailgate		<i>in</i> 1,050.00	X
2 pcs tailgate hinges (LH/RH)	@ S\$ 50.00	<i>in</i> 100.00	X
2 pcs tailgate damper (LH/RH)	@ S\$180.00	<i>in</i> 360.00	X
1 pc tailgate outer garnish		<i>in</i> 189.90	X
1 pc tailgate outer handle		<i>in</i> 175.50	X
1 pc tailgate logo		<i>in</i> 15.40	X
1 pc tailgate "VEZEL" emblem		<i>in</i> 43.00	X
1 pc tailgate lock		<i>in</i> 157.10	X
1 pc tailgate lock catch		<i>in</i> 27.50	X
1 pc tailgate weatherstrip		<i>in</i> 96.80	X
2 pcs tailgate lamp (LH/RH)	@ S\$276.90	<i>in</i> 553.80	X
1 pc tailgate inner trimboard - bottom		<i>in</i> 153.40	X
1 pc tailgate inner handle pocket		<i>in</i> 25.00	X
1 pc tailgate windscreen glass moulding		<i>in</i> 120.00	X
1 pc rear exhaust muffle		<i>in</i> 528.00	X
2 pcs taillamp assy (LH/RH)	@ S\$482.40	<i>in</i> 964.80	X
		6,284.20	
	Less 20% :	-1,256.84	
		5,027.36	

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : YN 8896 J
Our Ref : 020513

Page : 2
No. : 31494

- 1 pc rear bumper "TOTAL" logo sticker
- 1 pc rear end panel top garnish chrome
- 1 pc tailgate windscreen glass sealant
- 1 pc tailgate windscreen glass damping seal
- 1 pc reverse sensor
- 1 pc reverse camera
- 1 pc rear number plate

2012
na 200.00 sn
sn 250.00 sn *X*
na 40.00 sn *✓*
na 20.00 sn *✓*
sn 220.00 sn *X*
sn 380.00 sn *X*
sn 40.00 sn *X*

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

750.00 *500*

To focus taillamps. To check rear wiring and lighting operation.

50.00 *201*

To remove and refit rear windscreen glass and conduct water leak test

120.00 *✓*

To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works

na 120.00 *X*

To apply undersealing

120.00 *301*

To transfer tailgate's fittings

80.00 *601*

To remove and renew exhaust silencer box

120.00 *601*

To remove and refit reverse sensor assy.

80.00 *501*

Con't Page 3 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : YN 8896 J
Our Ref : 020513

Page : 3
No. : 31494

To putty and respray on affected
portions.

400/

1,000.00

Total : S\$ 8,617.36

=====

Singapore Dollars Eight Thousand Six Hundred
and Seventeen and Cents Thirty Six Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: