BW WORKSHOP SERVICES PTE LTD

291 KAKI BUKIT AVE 1 SHUN LI **INDUSTRIAL PARK** Singapore 416080 6289 8800

workshop_admin@bw.com.sg GST Registration No.: 201504834E Company Registration No. 201504834E



ADDRESS

AIG ASIA PACIFIC INSURANCE PTE. LTD.

ESTIMATES NO. 1223 **DATE** 13/11/2020

VIN NUMBER MAKE & MODEL **MILEAGE**

SMV835M / ZWR800403150 **TOYOTA VOXY HYBRID 1.8V**

| ACTIVITY | QTY | RATE | AMOUNT |
|---|-----|----------|----------|
| FRONT BUMPER @ \$1850 ✓ DIS | 1 | 2,035.00 | 2,035.00 |
| FRONT BUMPER RETAINER RH @ \$45 ✓ DIS | 1 | 49.50 | 49.50 |
| FRONT BUMPER RETAINER LH @ \$45 ✓ DIS | 1 | 49.50 | 49.50 |
| FRONT SPONGE @ \$45 ✓ DIS | 1 | 49.50 | 49.50 |
| FRONT REINFORCEMENT @ \$105 ✓ DIS | 1 | 115.50 | 115.50 |
| FRONT BUMPER LOWER GRILLE @ \$105 ✓ DIS | 1 | 115.50 | 115.50 |
| FOG LAMP BRACKET RH @ \$155 ✓ DIS | 1 | 170.50 | 170.50 |
| FOG LAMP BRACKET LH @ \$155 ✓ DIS | 1 | 170.50 | 170.50 |
| FOG LAMP COVER RH @ \$60 ✓ DIS | 1 | 66.00 | 66.00 |
| FOG LAMP COVER LH @ \$60 ✓ DIS | 1 | 66.00 | 66.00 |
| RAD AIR GUIDE @ \$55 ✓ DIS | 1 | 60.50 | 60.50 |
| ENGINE UNDER COVER RH @ \$130 ✓ DIS | 1 | 143.00 | 143.00 |
| ENGINE UNDER COVER LH @ \$130 ✓ DIS | 1 | 143.00 | 143.00 |
| FRONT BUMPER UNDER COVER @ \$65 ✓ DIS | 1 | 71.50 | 71.50 |
| GRILLE @ \$280 ✓ DIS | 1 | 308.00 | 308.00 |
| FRONT LOGO @ \$55 ✓ DIS | 1 | 60.50 | 60.50 |
| BONNET @ \$260 🗸 DIS | 1 | 286.00 | 286.00 |
| BONNET CHROME @ \$120 ✓ DIS | 1 | 132.00 | 132.00 |
| BONNET INSULATOR @ \$320 ✓ DIS | 1 | 352.00 | 352.00 |
| BONNET SEAL @ \$38 ✓ DIS | 1 | 41.80 | 41.80 |
| FENDER COWLING RH @ \$165 ✓ DIS | 1 | 181.50 | 181.50 |
| FENDER COWLING LH @ \$165 ✓ DIS | 1 | 181.50 | 181.50 |
| FENDER BRACKET RH @ \$50 ✓ DIS | 1 | 55.00 | 55.00 |
| FENDER BRACKET LH @ \$50 ✓ DIS | 1 | 55.00 | 55.00 |
| NETS & Cash only. | | | |

Our Bank Details:-Name of Bank: UOB

Account Name: BW Workshop Services Pte Ltd

| ACTIVITY | QTY | RATE | AMOUNT |
|--|-----|----------|----------|
| FRONT FENDER RH @ \$900 ✓ DIS | 1 | 990.00 | 990.00 |
| FRONT FENDER LH @ \$900 ✓ DIS | 1 | 990.00 | 990.00 |
| FRONT FENDER INNER RH @ \$105 ✓ DIS | 1 | 115.50 | 115.50 |
| FRONT FENDER INNER LH @ \$105 ✓ DIS | 1 | 115.50 | 115.50 |
| BONNET LOCK @ \$90 ✓ DIS | 1 | 99.00 | 99.00 |
| BONNET CABLE @ \$60 ✓ DIS | 1 | 66.00 | 66.00 |
| BONNET HINGE RH @ \$30 ✓ DIS | 1 | 33.00 | 33.00 |
| BONNET HINGE LH @ \$30 ✓ DIS | 1 | 33.00 | 33.00 |
| SUPPORT PANEL @ \$550 ✓ DIS | 1 | 605.00 | 605.00 |
| RAD SIDE GUIDE RH @ \$55 ✓ DIS | 1 | 60.50 | 60.50 |
| RAD SIDE GUIDE LH @ \$55 ✓ DIS | 1 | 60.50 | 60.50 |
| BRACE PANEL @ \$45 ✓ DIS | 1 | 49.50 | 49.50 |
| FRONT WHEELHOUSE LH @ \$320 ✓ DIS | 1 | 352.00 | 352.00 |
| PASSENGER LH (183600 ✓ ACT | 1 | 3,960.00 | 3,960.00 |
| DASHBOARD @ \$1160 ✓ DIS | 1 | 1,276.00 | 1,276.00 |
| FRONT WINDSCREEN @ \$750 ✓ CRA | 1 | 825.00 | 825.00 |
| FRONT WINDSCREEN MOULDING @ \$30 ✓ NEC | 1 | 33.00 | 33.00 |
| WIPER COWLING @ \$600 ✓ DIS | 1 | 660.00 | 660.00 |
| STEERING AIRBAG @ \$2680 ✓ ACT | 1 | 2,948.00 | 2,948.00 |
| FRONT SEATBELT RH @ \$960 ✓ ACT | 1 | 1,056.00 | 1,056.00 |
| FRONT SEATBELT LH @ \$960 ✓ ACT | 1 | 1,056.00 | 1,056.00 |
| FRONT CRASH SENSOR @ \$130 ✓ ACT | 2 | 143.00 | 286.00 |
| AIRBAG CONTROL UNIT @ \$1000 ✓ ACT | 1 | 1,100.00 | 1,100.00 |
| CLOCK SPRING @ \$960 ✓ ACT | 1 | 1,056.00 | 1,056.00 |
| HEADLAMP RH @ \$850 ✓ DIS | 1 | 935.00 | 935.00 |
| HEADLAMP LH @ \$850 ✓ DIS | 1 | 935.00 | 935.00 |
| HEADLAMP GARNISH RH @ \$45 ✓ DIS | 1 | 49.50 | 49.50 |
| HEADLAMP GARNISH LH @ \$45 ✓ DIS | 1 | 49.50 | 49.50 |
| FOG LAMP RH @ \$95 ✓ DIS | 1 | 104.50 | 104.50 |
| FOG LAMP LH @ \$95 ✓ DIS | 1 | 104.50 | 104.50 |
| RADIATOR @ \$580 ✓ DIS | 1 | 638.00 | 638.00 |
| RADIATOR TOP HOSE @ \$65 ✓ DIS | 1 | 71.50 | 71.50 |
| RADIATOR LOWER LOWER @ \$25 ✓ DIS | 1 | 27.50 | 27.50 |
| AIRCON FAN BLADE @ \$75 ✓ DIS | 1 | 82.50 | 82.50 |
| RAD FAN BLADE @ \$75 ✓ DIS | 1 | 82.50 | 82.50 |
| RAD FAN COWLING @ \$115 ✓ DIS | 1 | 126.50 | 126.50 |
| RAD MOTOR @ \$190 ✓ DIS | 1 | 209.00 | 209.00 |
| AIRCON MOTOR @ \$190 ✓ DIS | 1 | 209.00 | 209.00 |
| RAD SPARE TANK @ \$65 ✓ DIS | 1 | 71.50 | 71.50 |
| RAD TOP BUSH @ \$12 ✓ DIS | 2 | 13.20 | 26.40 |
| RAD LOWER BUSH @ \$20 ✓ DIS | 2 | 22.00 | 44.00 |
| NETS & Cash only. | | | |

Our Bank Details:-Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd

| ACTIVITY | QTY | RATE | AMOUNT |
|---|-----|-----------|-----------|
| RAD CAP @ \$55 ✓ DIS | 1 | 60.50 | 60.50 |
| WATER HOSE @ \$20 ✓ DIS | 1 | 22.00 | 22.00 |
| WATER HOSE @ \$10 ✓ DIS | 1 | 11.00 | 11.00 |
| WATER HOSE @ \$12 ✓ DIS | 1 | 13.20 | 13.20 |
| EGR COOLER @ \$650 ? | 1 | 715.00 | 715.00 |
| EGR VALVE @ \$750 ? | 1 | 825.00 | 825.00 |
| EGR PIPE @ \$130 ? | 1 | 143.00 | 143.00 |
| INTAKE MANIFOLD @ \$320 ✓ DIS | 1 | 352.00 | 352.00 |
| AIR CLEANER ASSY @ \$350 ✓ DIS | 1 | 385.00 | 385.00 |
| AIR CLEANER DUCT TOP @ \$110 ✓ DIS | 1 | 121.00 | 121.00 |
| AIR CLEANER DUCT LOWER @ \$35 ✓ DIS | 1 | 38.50 | 38.50 |
| RESONATOR @ \$30 ✓ DIS | 1 | 33.00 | 33.00 |
| AIR CLEANER BRACKET @ \$25 ✓ DIS | 1 | 27.50 | 27.50 |
| WASHER TANK @ \$60 ✓ DIS | 1 | 66.00 | 66.00 |
| WASHER TANK NECK @ \$25 ✓ DIS | 1 | 27.50 | 27.50 |
| WASHER TANK MOTOR @ \$90 ✓ DIS | 1 | 99.00 | 99.00 |
| WIPER BLADE RH @ \$65 ✓ DIS | 1 | 71.50 | 71.50 |
| WIPER BLADE LH @ \$35 ✓ DIS | 1 | 38.50 | 38.50 |
| ENGINE MOUNTING FRONT @ \$80 ✓ BT | 1 | 88.00 | 88.00 |
| ENGINE MOUNTING BKT FRONT @ \$90 ✓ BT | 1 | 99.00 | 99.00 |
| ENGINE MOUNTING LH @ \$240 ✓ BT | 1 | 264.00 | 264.00 |
| ENGINE MOUNTING BRACKET LH @ \$105 ✓ BT | 1 | 115.50 | 115.50 |
| ENGINE MOUNTING REAR @ \$305 ? | 1 | 335.50 | 335.50 |
| ENGINE MOUNTING BRACKET REAR @ \$80 ? | 1 | 88.00 | 88.00 |
| ENGINE MOUNTING RH @ \$410 ✓ BT | 1 | 451.00 | 451.00 |
| ENGINE MOUNTING BRACKET RH @ \$170 ✓ BT | 1 | 187.00 | 187.00 |
| GEARBOX ASSY @ \$10520 ? | 1 | 11,572.00 | 11,572.00 |
| FRONT DRIVESHAFT LH @ \$1130 ✓ DIS | 1 | 1,243.00 | 1,243.00 |
| FRONT SHOCK LH @ \$450 ✓ DIS | 1 | 495.00 | 495.00 |
| FRONT SHOCK RH @ \$450 ? | 1 | 495.00 | 495.00 |
| FRONT LINKAGE @ \$65 ? | 2 | 71.50 | 143.00 |
| FRONT STABILIZER BAR @ \$380 ? | 1 | 418.00 | 418.00 |
| FRONT BAR BUSH @ \$12 ? | 2 | 13.20 | 26.40 |
| FRONT BAR BUSH BRACKET @ \$12 ? | 2 | 13.20 | 26.40 |
| FRONT SHOCK TOP MOUNTING @ \$220 ? | 1 | 242.00 | 242.00 |
| FRONT SHOCK TOP SEAL @ \$15 ? | 2 | 16.50 | 33.00 |
| FRONT SHOCK STOPPER @ \$15 ? | 2 | 16.50 | 33.00 |
| FRONT KNUCKLE RH @ \$175 ? | 1 | 192.50 | 192.50 |
| FRONT KNUCKLE LH @ \$175 🗸 DIS | 1 | 192.50 | 192.50 |
| FRONT LOWER ARM LH @ \$250 ✓ DIS | 1 | 275.00 | 275.00 |
| FRONT LOWER ARM RH @ \$250 ? | 1 | 275.00 | 275.00 |
| NETS & Cash only | | | |

NETS & Cash only.

Our Bank Details:-Name of Bank : UOB

Account Name: BW Workshop Services Pte Ltd

| ACTIVITY | QTY | RATE | AMOUNT |
|---|-----|-----------|----------------------|
| STEERING RACK @ \$1850 ? | 1 | 2,035.00 | 2,035.00 |
| TIE ROD END LH @ \$45 ? | 1 | 49.50 | 49.50 |
| TIE ROD END RH @ \$45 ? | 1 | 49.50 | 49.50 |
| ENGINE HARDNESS WIRE @ \$8000 ? | 1 | 8,800.00 | 8,800.00 |
| FRONT ENGINE HARDNESS WIRE @ \$200 🙃 🗸 🗸 BR | 1 | 220.00 | 220.00 🗸 |
| LH FUSE BOX TOP @ \$100 ✓ DIS | 1 | 110.00 | 110.00 |
| LH FUSE BOX CENTER @ \$200 ? | 1 | 220.00 | 220.00 |
| LH FUSE BOX LOWER @ \$100 ? | 1 | 110.00 | 110.00 |
| ROOF AIR BAG LH @ \$2850 ✓ ACT | 1 | 3,135.00 | 3,135.00 |
| INVERTOR @ \$5070 ? | 1 | 5,577.00 | 5,577.00 |
| ROOF LINING @ \$4500 ✓ CRUMP | 1 | 4,950.00 | 4,950.00 |
| DRIVER KNEE AIRBAG @ \$550 ✓ ACT | 1 | 605.00 | 605.00 |
| RH LEFT CURTAIN AIRBAG @ \$2850 _? ✓ ACT | 1 | 3,135.00 | 3,135.00 🗸 |
| PASSENGER SEAT SIDE AIRBAG @ \$950 ✓ ACT | 1 | 1,045.00 | 1,045.00 |
| DRIVER SEAT SIDE AIRBAG @ \$950 ✓ ACT | 1 | 1,045.00 | 1,045.00 |
| FRONT WHEEL BEARING @ \$55 ✓ DIS | 1 | 60.50 | 60.50 |
| FRONT BRAKE ROTOR (LH) @ \$110 ? | 1 | 121.00 | 121.00 |
| FRONT BRAKE CALIPER (LH) @ \$380 ? | 1 | 418.00 | 418.00 |
| HYBRID EMBLEM @ \$40 ✓ NEC | 2 | 44.00 | 88.00 |
| FRONT BUMPER CLIPS @ \$15 ✓ NEC | 20 | 16.50 | 330.00 |
| TYRE @ \$120 ? | 1 | 132.00 | 132.00 |
| DRIVER LEATHER SEAT @ \$450 ? ✓ DIS | 1 | 495.00 | 495.00 🗸 |
| FRONT PASSENGER LEATHER SEAT @ \$450 - ? ✓ DIS | S 1 | 495.00 | 495.00 🗸 |
| AVAS @ \$408 ? ✓ DIS | 1 | 448.80 | 448.80 🗸 |
| ENGINE @ \$15135 ? | 1 | 16,648.50 | 16,648.50 |
| INVERTER COOLANT @ \$1662 - → ✓ DM | 1 | 1,828.20 | 1,828.20 ✓ |
| MAIN HARDNESS @ \$6309 2 ✓ BR | 1 | 6,939.90 | 6,939.90 🗸 |
| | | | Subtotal: 105,980.60 |
| LABOUR | | | |
| TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS. | 45 | 200.00 | 9,000.00 1800 |
| TO PUTTY AND RESPRAY ON AFFECTED PORTIONS | 13 | 200.00 | 2,600.00 2200 |
| TO TOW ACCIDENT VEHICLE TO WORKSHOP BY FLATBED OR KINGS DOLLY TOWING | 1 | 250.00 | 250.00 ? |
| TO FOCUS HEADLAMPS . TO CHECK WIRING AND LIGHTING OPERATION | 1 | 120.00 | 120.00 20 |
| TO FOCUS FOG LAMPS . TO CHECK WIRING AND LIGHTING OPERATION | 1 | 120.00 | 120.00 20 |
| TO REMOVE AND REFIT REAR UPHOLISTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING | 1 | 1,800.00 | 1,800.00 400 |
| NETS & Cash only. | | | |

Our Bank Details:-Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd Account Number :356-305-177-7

| Please feel free to contact us again if you have any queries on our quotation. | SUBTOTAL GST TOTAL | | 139,400.60 0.00 | |
|--|-----------------------|----------|---------------------|-----------------|
| | | | Subtotal: 33,420.00 | |
| TO REMOVE AND REFIT GEAR BOX IN ORDER TO FACILITATE REPAIRING WORKS | 1 | 800.00 | 800.00 | ? |
| TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST | 1 | 120.00 | 120.00 | |
| TO REMOVE DOOR GLASS. VACUMN AND CLEAN UP GLASS | 4 | 120.00 | | × NN |
| TO REMOVE, RENEW VALVE COVER AND REACKER AIM, CAM SHAFT, DECARBORNE AND RENEW CYLINDER HEAD | 1 | 800.00 | 800.00 | × _{NN} |
| TO OVERHAUL ENGINE AND RESTART ENGINE | 1 | 3,200.00 | 3,200.00 | \times NN |
| TO DISMANTLE AND TRANSFER GEARS MECHANISM TO NEW HOUSING | 1 | 800.00 | 800.00 | \times NN |
| TO REMOVE AND RENEW EXHAUST SILENCER BOX | 1 | 150.00 | 150.00 | × NN |
| SPECIFICATION TO REMOVE AND RENEW FRONT EXHAUST MANUFOLD AND EXHAUST FRONT PIPE | 1 | 260.00 | 260.00 | × NN |
| TO PLACE VEHICLE ON CELETE BENCH AND TO REALIGN CAR BODY ACCORDING TO | 1 | 2,000.00 | 2,000.00 | 500 |
| TO CONDUCT FRONT WHEEL ALIGNMENT TEST | 1 | 120.00 | 120.00 | 60 |
| TO DISMANTLE AND CHECK FRONT UNDERCARRIAGES. TO REPLACE AFFECTED PORTIONS | 1 | 800.00 | 800.00 | 200 |
| TO REMOVE AND REFIT ENGINE ASSY IN ORDER TO FACILITATE REPAIRING WORKS | 1 | 3,200.00 | 3,200.00 | 250 |
| TO REMOVE AND TRANSFER DOOR'S FITTINGS | 2 | 200.00 | 400.00 | 80 |
| TO REMOVE FRONT BRAKE BOOSTER, BRAKE MASTER PUMP AND STEERING COLUMN | 1 | 700.00 | 700.00 | ? |
| TO REMOVE AND RENEW AIR BAG SENSORS SEAT BELTS ASSY, TO REWIRING AND RE- SETTING PROGRAM | 1 | 1,600.00 | 1,600.00 | 200 |
| TO REMOVE FRONT INSTRUMENT PANEL AND REWIRING TO FACILITATE REPAIR WORKS | 1 | 1,800.00 | 1,800.00 | 250 |
| REPAIRING WORKS TO APPLY UNDERSEALING | 1 | 800.00 | 800.00 | 120 |
| TO REMOVE AND REFIT FRONT SEAT ASSY TRIMBOARD AND CARPET TO FACILITATE | 1 | 1,500.00 | 1,500.00 | 80 |
| WORKS | QTY | RATE | AMOUNT | |
| A O TIV (IT) (| OTV | D. 177 | | |

NETS & Cash only.

Our Bank Details:-Name of Bank: UOB

Account Name: BW Workshop Services Pte Ltd

Accepted By Accepted Date

LKK Auto Consultants hence notify

- are respense or any ronouning;
- · To display demand parties during recurren
- Parts orions are subject to confirmation
- . Third party survey is on a "Without Projuding" basis
- No Begal modification(a) is allower
- Supplementary item(s) must be recurveyed god is subject to final approval from insurance Communications.

Admostedged by Repairs

Date:

NETS & Cash only.

Our Bank Details:-Name of Bank : UOB

Account Name : BW Workshop Services Pte Ltd