

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 26 Nov 2020

Preliminary Advice

Vehicle No	: SMV835M	Accident Date	: 26/10/2020
Make	: TOYOTA VOXY HYBRID	Policy No.	: 2070134931
Assignment Date	: 29/10/2020	Excess	: S\$600.00
Date of Inspection	: 28/10/2020	Est. Duration of Repair	: -
Inspection At	: BW WORKSHOP SERVICES PTE LTD (HQ) 291 KAKI BUKIT AVENUE 1, SHUN LI INDUSTRIAL PARK SINGAPORE 416080		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	139,400.60
Revised Amount	:S\$	62,557.30
Check Items (Estimated)	:S\$	51,473.30
Total	:S\$	114,030.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	134,000.00
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	65,753.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	68,247.00
Margin for Repair (Pre-Accident Value)	:S\$	54,247.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Margin for Repair (New for Old Value) is \$68,247.00, Margin for Repair (Pre-Accident Value) is \$54,247.00