

AIAsia Insured's Veh No : SKR1577X
Date of Accident : 27 October 2020


陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 28 October 2020

Estimate To Repair SMA980L - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7208508

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	o/s rear door	\$ 1,309.00
02	1 pc	o/s rear door lock	\$ 229.00
03	2 ps	o/s rear door hinge @ \$65.00	\$ 130.00
04	1 pc	o/s rear door top moulding	\$ 85.00
05	1 pc	o/s rear door weatherstrip	\$ 105.00
06	1 pc	o/s front door	\$ 1,409.00
07	1 pc	o/s front door outer handle	\$ 187.00
08	2 ps	o/s front door hinge @ \$65.00	\$ 130.00
09	1 pc	o/s front door power window motor	\$ 310.00
10	1 pc	o/s front door power window regulator	\$ 229.00
11	1 pc	o/s front door weatherstrip	\$ 105.00
12	1 pc	o/s front door top moulding	\$ 85.00
13	1 pc	o/s front fender	\$ 1,223.00
14	1 pc	o/s side mirror assy	\$ 652.00
15	1 pc	o/s rocker panel	\$ 988.00
Less 10 %			\$ 7,176.00
			\$ 717.60
			\$ 6,458.40
LABOUR & MISC. CHARGES			
01		To transfer of o/s front and rear door fittings and perform water seepage test.	\$ 200.00
02		To replace o/s side mirror.	\$ 50.00
03		To rust-proofing of the affected areas.	\$ 150.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,100.00
05		Putty and spray painting of the affected portion.	\$ 1,000.00
			\$ 2,500.00
Total			\$ 8,958.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: